

When we removed the barrel action from the stock assembly, the trigger assembly was wet with excessive oil. The use of oil should be used sparingly on the firearm and not let accumulate in or on the trigger assembly, as this condition could adversely affect the operation of the trigger assembly.

Mr. Perrigo, as a gesture of good-will, we are requesting that our repair service section install a new trigger assembly at no charge, and return your rifle to you. The firearm will also be re-tested in our shooting gallery before we effect shipment.

We trust our action meets with your approval.

Sincerely,

  
D.V. Sanita  
Product Service

DJS:tp

*Remington Arms Company, Inc.*