

*Remington.*



**REMINGTON ARMS COMPANY, INC.**

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

February 28, 1986

Mr. Johnny Rizzo  
2800 Camelot  
Bryan, TX 77802

Dear Mr. Rizzo:

Examinations have been completed on your Model 700 ADL, serial number 667935 and on your Mohawk 600, serial number 6785931, which you sent relative to accidental firings.

The Model 700 trigger adjustment screw, as you stated, was backed out through the seal. However, our experts maintain there is no way the screw could have broken the seal and backed out on its own. It had to have been worked on to do so. Other than that situation, we found no defects in the fire assembly or in the rifle. Therefore, we are going to readjust the trigger to factory specifications and return the firearm to you at no charge.

Your Mohawk 600 was produced in August, 1974 and contains our gallery, proof and final inspection stampings, indicating it had passed all tests, both metallurgically and manufacturing-wise, prior to shipment.

The general overall condition of the gun is very good and measurements taken on the trigger pull showed a consistent 4.5 lb pull which is within manufacturing specifications.

Measurements taken on the entire spectrum of the sear lift, which is the distance the sear raises from the trigger connector when the safety switch is rotated from on to off and off to on, was within our manufacturing tolerances. Also, we could not manipulate the bolt, safety or trigger in any manner that would allow the firearm to fire unless the safety switch was off and the trigger pulled, which it was designed to do.

Based on our findings, Remington Arms Company, Inc., cannot assume any responsibility or liability for your room damage.