

RECEIVING AND ESTIMATING REPORT

THRU MTS ONLY

STEKO

SR 1 Box 27-A
Walton WV 25286ORDER
91-18337WV
25286VIA
UPS

TOTAL

☐ MARRED+ springs
units with a
carefully
maintained
trigger assembly

This gun has a fault in the firing mechanism. It worked ok the first hunting season, but I only fired it 5 times in the woods.

The second season when I took it for practice to see if the scope was aligned, it discharged automatically. Therefore, I did not take it in the woods.

I tried to get it fixed locally, but they said it must be returned to the company. I thought that this might be one of the ones on recall. Since it mis-fired after relatively no use, it must be a defect from the factory.

If there is a charge, please let me know, but I feel Remington should repair this without charge. I have had good service with Remington in the past, and feel this is not Remington quality.

Earl M. Shafer

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
172					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

REV. 7/9