

BARBER - Kinzer PPS GAL RE0004539

RECEIVING AND ESTIMATING REPORT

ORDER R92-15318

COMMENTS: L/FLOOR PLATE, SCREWS
ATTN: HERB BROWN

DATE RECEIVED: 7/17/92 DATE OPENED: 07/29/92 DATE CODE: KS 5-69 SERIAL NUMBER: 6239535 NEW SERIAL NUMBER: MODEL AND GRADE: 700 243 WIN VAR

ACCESSORIES: L/WOOD L/FOLLOWER L/MAG SPRING L/REAR SIGHT

FROM: SHRIVER, ROBERT E
1605 HUFFMAN DR
WARREN OH 44481

SHIP TO: SHRIVER, ROBERT E
1605 HUFFMAN DR
WARREN OH 44481

CUST NO: 064241 C.O.D. L

COUNT NUMBER: ACCOUNT NUMBER NC: WRITE ☐ CLEAN/TEST FROM DATE: ESTIMATED: VIA: UPS

IN CONDITION: NEW LIGHTLY WORN WORN VERY WORN UNREPAIRABLE MARRED

REPAIR CHARGE: EXCISE TAX INSURANCE UPS PARCEL POST TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1			E1	F1
TRIGGER GROUP		B2			E2	F2
SLT ASSY.		B3			E3	F3
BARREL ASSY.		B4		D1	E4	F4
EC. ASSY.		B5		D2	E5	F5
WOOD			C1	D3		
ETAL			C2			

IN FAULT: Trigger assembly has been improperly adjusted outside factory. Sealant is missing from pull adjustment and over travel screws. Trigger assembly could be duplicated, because trigger pull was misadjusted on light (2 pounds) was too light. Trigger spring broke left to keep trigger under rear sight. Trigger pull 2 1/2 lbs. from left. 0081

NOTE: Customer request O.S. Safety

RTS: COMMENTS: Here adjust present trigger assembly to minimum spec - 3 1/2 pounds, etc.

2) Offer new trigger assembly at a normal cost, as guarantee of good work, all at 3 1/2 pounds

REPAIRMAN: PROOF: CLEAN: TEST: TARGET: PATTERN:

GALLERY TESTER: DATE: DATE: DATE: DATE: DATE: