Remington Arms Co., Inc.
Product Service
Legal Case #:2601

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete
148948 8/8/2008 8/13/2008 8/13/2008

Customer Information

City Zip Age Contact Type Business First Name Last Name Street State H 417-934-1569 8500 County Rd 3940 W 417-934-2291, ext 233 Incident Kevin Conner Mountain View MO 65548 C417-247-0971

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Scope hole damaged in receiver Cause:4006 Altered Adjustments or Components Concern:1007 Fired on Safe Release

Unknown

S Fired on Safe release

C

Blocker was not returning trigger under sear due to altered adjustments. Scope hole in receiver was damaged by customer - he broke the screw off in the hole and damaged the hole further trying to remove the broken piece.

Firearm Information

Model/Ga. SKU Mfg. Type Serial Bbl. DOM CF/BA 700/7mm Rem Ma 27047 G6636738 BB 1/16/2007 10:48:21 PM Remington **Date Purchased** Accessories **Original Owner** Where Purchased SIMMONS GUN SPECIALTIES I U

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement Reim. Date APV Cash Date APV

Repair/Replacement Cost Repair/Replacement Date

8/13/2008 Returned to AS to try to repair the scope hole - if it is not repairable we will quote the customer for a new barreled action at 1/2 normal charges and install a new TA fls.

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	27.26
	Examiner]	Supry	77.26
	Exam Date]	8/13/2008	
Examination	Product Type]	RF	
;	Action Type]	A	
	Assigned To]	Supry	
Cause	4006	Altered Adjustments or Components	Blocker adjusted improperly. Scope mount hole damaged by customer	
	Description]	26 inch Model 700 7mm Rem Mag	
	Date Code]	ВВ	
	Bore Plugged	False		
Barrel	Bulged	False		· •
Barrei	Fired	False		,
	Fired while Obstructed			
	Muzzle/Crown			

l	Condition	Like new; Functioning		
	Firing Pin	Slightly Worn; Functioning		
Bolt	Shroud	Slightly Worn; Functioning		
	Face	Slightly Worn; Functioning		
	Handle	Slightly Worn; Functioning		_
	Stop	Slightly Worn; Not Functioning	Stop was sticking due to sticky residue.	
	Condition	Slightly Worn; Functioning		
Extractor	Cut Condition	Slightly Worn; Functioning		
	Ext/Eject Test	True		
	Block Condition	Select		
Locking	Lug Condition	Like new; Functioning		
	Notch Condition	Select		
M	Condition	Select		
Magazine	Box Condition	Like new; Functioning		
	Exterior Condition	Slightly Wom; Functioning	some surface rust	
Overall	Stock Condition	Like new; Functioning		
	Fore End Condition	Select		
Receiver	Condition	Slightly Worn; Functioning	some rust near the port area	
	Bulged	False		
	Description		Model 700]
Safety	Function	Like new; Functioning		
	Sub-Assembly	Non-ISS		
Sear	Lift	Select	not measured]
	Notch	Like new; Functioning		
		Condition	Abused; Functioning	Blocker adjusted so it is not returning the trigger under the sear
Pull	Trioger	Select	3 1/4 lbs	
Altered	Trigger	True		-
Sub- Assembly		X-Mark Pro		

Contact / Condition Contact Co	Address Information Customer: Name: KEVIN CONNER Address 1: 8500 COUNTY ROAD 3940 Address 2: MOUNTAIN VIEW State: MO Zip Code: 65548 Contact / Condition: Pr	PO-Box J	Sceived From Ret	Tun To: EVIN CONNER OD COUNTY ROAD 3940 DUNTAIN VIEW D Zip Code: (65548	PO Box	ved From
Address 1: 9500 COUNTY ROAD 3940 Address 2: PO Box PO Box City: MOUNTAIN VIEW PO Box State: MO Zip Code:	Address 1: 8500 COUNTY ROAD 3940 Address 2: City: MOUNTAIN VIEW State: MO Zip Code: 65548 Contact / Condition Pr	Cour	IB5 INITY IUS State: IMC	OO COUNTY ROAD 3940 DUNTAIN VIEW D Zp Code (65548		S
Contact / Condition Problems Estimate History / Status Shipping / Biding Date Code UserID Desc1 Shipping Hold Closed 8/8/2008 5:28.56 New brygidowwr Repair Added Closed B/8/2008 5:28.34 PM 8/8/2008 5:28.34 Closed brygidowwr Repair Added Closed Estimate Sent Brygidowwr 8/8/2008 7:17:5 Comment supryll Returned for special price repair Parts Received Repair Location 1	Dale Code L	Problems .	Version Problems and Problems	Y	I I	
Repair Search Close Close	8/8/2008 5:28:34 Closed I	prydigowwr prydigowwr	Repair Added Closed at Expedite	F Shipping Ho F InterFace H e repair F Estimate Sei Parts Receir Passed Insp Return As R Has been A	Current Id Circle Id Cro Id 8/8/2008 In I	Status sted 5:28:34 PM dowwi Services Location N Location N
	Repair Search				<u>R</u> efresh	Close
	8/13/8		26 AM - VICAPS	Num		



d 2601

July 30, 2009

To: Remington Arms
Attn: Arms Services
14 Hoefler Avenue

Ilion, NY 13357

From: Kevin Conner

8500 County Road 3940 Mountain View, MO 65548

Home: 417-934-1569 Cell: 417-247-0971

Home: 417-934-2291 ext. 233

Trigger Assembly
screw settings edinsted,
scope screw hole
assistant of broken
prece in hole
Repair if passible if
not offer new borreled
Action of & normal charges
and instead new TA.

FLS 8/13/08

Dear Sirs:

Enclosed is my Remington Model 700 CDL, serial number G6636738, 7 MM REM MAG.

While hunting this past winter, I took my gun off safety and when I did the gun discharged. I would appreciate you checking this problem out for me. Also, when I was taking off the scope to prepare for shipping, I broke a screw off in the scope mount. I also ask that you tap that hole out for me.

If you need to contact me, I have enclosed my home, cell and work number.

Sincerely,

Kevin Conner

G6636738

148948

#2621

M KENZN CONNER

ldd	ress			
ieg	. No. Clark	Account Forward		
1	REM 7mm CDL		710	00
	(2) LEUP. 4.5x/4		1200	00
3	LEUA RINGS BASE	5	1 45	00
4			1955	00
5	Tagan samaha samahang pempelan da paga 1 samp damaha paga 1 samp damaha samp samp	TAX	136	85
6			2091	85
7		\leq		
8		20		
9	, 14	7	-	
10				
17				
12	1			
13	· · · · · · · · · · · · · · · · · · ·			
14	And the state of t			
15	7376=73			