Remington Arms Co., Inc. **Product Service** Legal Case #:1926

Case Information

Incident Date Lit Obsolete Date Opened(PS) **Date Closed** Pre Lit RE# **Date Opened**

1/3/2008 1/3/2008 138816 12/28/2007

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

H 636-433-2580

Engemann 15401 Engemann Lane Marthasville MO 63357 W 314-234-0137 Reporter Doug

E douglas.g.engemann@boeing.com

Incident Information

Codes Repair Est. Medical Treatment Medical Status Claims

PΙ

PD Cause:4006 Altered Adjustments or Components

S fires on safe release Concern: 1007 Fired on Safe Release

Unknown

1/9/08-correspondence from repair-cust lightened trigger to help with accuracy. Rifle fired on safe release. Wants x mark pro.lw

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial Bbl.

DOM

Remington

CF/BA

700/300 WIN MA

27313

S6585150 RA

11/6/2006 8:08:28

Date Purchased

Where Purchased

SPORT

Accessories

Original Owner

AM

GLENN ZANDERS FUR &

TWO PIECE SCOPE BASE, RINGS

U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date

Reimbursement

Cash Settlement Reim. Date APV

Cash Date APV

Replace TA at discount

Repair/Replacement

Repair/Replacement

Cost

Date

1/9/08-Replace TA at discount.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Date		1/3/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4006	Altered Adjustments or Components	SET SCREWS ALTERED
	Description		26" 300 WIN MAG FL SS
	Date Code		RA
	Bore Plugged	False	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=1926&Type=Case

1/9/2008

BARBER - Kinzer PPS GAL RE0008429

1	Bulged	False	ាំ
Barrel	Fired	False]
	Fired while Obstructed	Jr disc	1
	Muzzle/Crown Condition	I ika maya Damatianina	٦
		Like new; Functioning	1
	Firing Pin	Like new; Functioning	<u> </u>
Bolt	Shroud	Like new; Functioning	<u>]</u> 1
	Face	Like new; Functioning	1
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	
	Condition	Like new; Functioning	
Extractor	Cut Condition	Like new; Functioning	
	Ext/Eject Test	False	j
	Block Condition	Select]
Locking	Lug Condition	Like new; Functioning	
	Notch Condition	Select	
	Exterior Condition	Like new; Functioning	
Overall	Stock Condition	Like new; Functioning]
	Fore End Condition	Select	
Danairon	Condition	Like new; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/700 X-MARK PRO
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	.012
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Like new; Functioning]
	Pull	Select	3#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	X-Mark Pro	
Non-Remington Components	Description] .	TWO PIECE SCOPE BASE,RINGS

Imis Scavices Repair Clastimate Sy Add Repair Estimate Repair : Expedite R Repair Impury		pols Reports Table Maintenance	System Maintenance	Help	
	enal: \$65851,50: Model 700: Center Fre ich bairel: Caliber: 300: WIN, MAG: \$5: \$F ENDERO: Produced: 11706/2006		12/26/2007 3.12.27 F	PM	
Address Information Customer 1991 1891 Name: DOUG ENGEMANN	P	etuin_Io: DOUG ENGEMANN	☐ Received Fro	om	
Address 1: 15401 ENGEMANN LANE Address 2: Cip: MARTHASVILLE State: MO Zip Code: 63357	PO Box	IARTHASVILLE	O Box		
12/26/2007-3:12 brygidowwr Repair A	Desc2- idded d to AS for repair at special price	History 7 Status Shipping Hold Interface Hold Interface Hold Parts Received Passed Inspector Return As Received Has been Approve	ed Current Locati	27 PM	
Repair <u>S</u> earch		Re	frēsh <u>C</u> I	ose	
supryfl	8 1252 PM (CARS	S NUMBER OF THE	A UN AUSCRI		

Remington Arms Attention: Arm Services 14 Hoefler Avenue Ilion, NY 13357

December 12, 2007

7 2 26"
3t 26"

To Whom It May Concern:

Enclosed please find the Remington 700 Sendero 300 Win Mag that I purchased last year. I ordered the gun in July and didn't get it until December, after our deer season had past here in Missouri.

I was not completely satisfied with the accuracy I was getting from the gun so my brother-in-law recommended I get the trigger lightened. A gunsmith in Ruston, LA lightened the trigger to about 2.5 pounds, which seemed to help.

During this deer season while I was hunting, I saw a deer and flipped the safety to the fire position. The gun immediately discharged! I was able to bolt the gun and shoot the deer as well as another one which came after it. After I got down from the tree stand, I unloaded the gun and adjusted the safety to the safe position. When I flipped it to the fire position, it dry fired. I did this probably ten times in a row and every time the gun would dry fire.

I spoke to your Customer Service department today, and they suggested that I send it to you. I am asking that you do the following:

- 1) Assess what is wrong with the trigger mechanism of the gun.
- 2) Notify me of the results of your investigation at the following contact information: Work 314-234-0137, Home 636-433-2580, E-mail douglas.g.engemann@boeing.com
- 3) Provide me an estimate of the cost of putting in a new X-Mark Pro Trigger. Please note that if I decide to put in the X-Mark Pro Trigger, I would want it lightened to the <u>minimum</u> of factory specifications.

Please advise me of your findings as soon as you can and thank you for your attention in this matter.

Sincerely yours

Doug Engemann

15401 Engemann Lane

Marthasville, MO 63357.
COULDNOT Duplicate concern
This, Set Schews ALTERED.

replace TAA, check over, clear

AT 1/2 NOTIMAL CHANGES, SET Thing: pull to min Ructory specs.

S6585150

RE00138816