Remington Arms Co., Inc. Product Service

Legal Case #:4865

Case Information

**Date Opened** Date Opened(PS) **Date Closed** Incident Date Pre Lit Obsolete RE# Lit

11/3/2010 11/4/2010 209231 10/27/2010

Customer Information

Last Name Street City Zip Type Business First Name State Age Contact H 814-796-6931

1605 Lane Rd Incident Richard Edinger Waterford PA . 16441 E edinger3108@roadrunner.com

Incident Information

Claims Codes Repair Est. **Medical Treatment** Medical Status

PI minor cut thumb

Could Not Duplicate Concern Cause:4038

N S FSR twice Concern: 1007 Fired on Safe Release

10/27/10 Per call to Edinger, about 2 yrs ago when deer hunting, he took the safety off and it fired. It is a left hand rifle and he thought he made the error. A few weeks ago he put a sope on and fired a shot then chambered a 2nd shot, closed the bolt and when he removed the safety it fired.cm

Firearm Information

Mfg. Model/Ga. SKU Type Serial Bbl. DOM CF/BA 700/30-06 SPR E6338719 BR 1/7/1997 n/a Remington Original Date

Where Purchased Accessories Purchased Owner

**ACUSPORT** SCOPE BASE AND BOTTOM HALF OF U CORPORATION RINGS

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Cash Cash Reim. Release of Claims Release Date Settlement Reimbursement Date Settlement Date APV APV

Per Ilion, replace TPA, test at 1/2 normal charges

## Repair/Replacement Cost Repair/Replacement Date

10/27/10 Sending ARS by email. He needs his rifle back by end of Nov for deer season.cm 11/8/10 Per Ilion, could not duplicate concern. Action and TPA dirty and a white substance on barrel and stock when removed. Check over, replace TPA, clean and test fire at 1/2 normal charges.cm 11/11/10 Left message for Edinger with inspect notes and estimate. Also emailed a copy of the quote.cm 1/6/11 Left detailed voice message for Richard regarding the repair, findings, the GR test (firing the rifle), and the confusion he may have had when I initially spoke with him and offered to pay shipping into the factory for a free inspection. Inspection would determine if this was warranty, however since this was a maintenance issue, we discounted repair but it was not a warranty repair cm 1/10/11 Edinger called and he said he did not feel comfortable with this rifle and would not use it or sell it. I asked him how he cleaned the rifle. He uses gun oil and gun cleaner. I asked him if he removed the stock to clean the trigger. He said no he did not know to do that. I mentioned it was in the manual and he said he hadn't looked at the manual. I'm mailing him a manual to have on hand in case he does ever use or sell this rifle.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
	Examiner	-	B.TRAVIS	
	Exam Date		11/4/2010	
Examination	Product Type		RF	
	Action Type		A	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4865&Type=Case

1/10/2011

•	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
	Description		22" 30-06 SPR
	Date Code		BR
Barrel	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		•
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	ACTION VERY DIRTY
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.013
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	10313	False	
	Condition		DIRTY
<b>Frigger</b>	Pull	Select	4.5#
I HEROI		False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE BASE AND BOTTOM HALF OF RINGS

Reference 101125-00	
Status Unresolve	d
Assigned Administra Christy -	
Product History	
SLA Not specif	

Queue

**Date Created** 

Initial Response

Last Updated

11/25/2010 10:26 AM

12/01/2010 11:11 AM

**Customer SmartSense** 

+1 (on -3 to +3 scale)

Staff SmartSense

0 (on -3 to +3 scale)

CSR

None

## fire while removing the safety

#### **Discussion Thread**

Customer (Dick & Donna Edinger)

11/25/2010 10:26 AM

I SENT MY REMINGTON 700 IN FOR REPAIR AS THE RIFLE FIRED LIVE ROUNDS WHILE I REMOWED THE SAFETY. I SENT A DETAILED LETTER TWICE ALONG WITH THE RIFLE AS TO WHAT OCURRED. I ASKED FOR A EXPLANATION AS TO WHAT CAUSED THIS TO WHAT HAPPENED. YOUR RESPONSE WAS THAT THE RIFLE WAS DIRTY AND YOU COULD NOT DUPLICATE THE PROBLEM. THE TEST GRIEST I DO NOT UNDERSTAND. THIS PROBLEM OCCURED AFTER LIVE ROUNDS WERE FIRED. I DO NOT KNOW IF THIS WAS INCLUDED IN YOUR TEST AS I REQUESTED. I PAID 91.16 FOR THE REPAIR THAT I AM NOT CONVINCED THAT SOLVE THE PROBLEM. I REQUEST A AUTHORIZATION THAT THIS RIFLE IS IN SAFE CONDITION. THE INVOICE IS 42352919 ON 11/19/2010. I WAS ALSO WAS TOLD THAT SHIPPING WAS TO BE PAID BY REMINGTON BUT THAT WAS NOT TRUE.

### **Primary Contact**

First Name: Dick & Last Name: Donna Edinger Organization:

Login: edinger3108@roadrunner.com Title:

Contact Type:

Email: edinger3108@roadrunner.com

Email - Alternate #1: Email - Alternate #2:


> Office Phone: Mobile Phone: Fax:

Assistant Phone: Home Phone:

> Street City State/Province Postal Code Country

**Additional Information** 

http://remington.custhelp.com/cgi-bin/remington.cfg/php/admin/display/inc print.php?p sid=51... 1/6/2011



## Workers Portugue

Dear Remington Repair

This sifle has

fired twice while

Taking the sufety

off a without my

finger on the

Trigger.

In afraid of

The sifle.


Trucke or give

this rifle away.

#E6338719 Model: 700



RE00209231




4865

Quote: 1/2 price TPA \$57.50 17.sky
11.50
test
+ax
91.16

could not dup liente concern.
Action/TPA DIRTY AND A White
Substance on BBL+STK when
removed. check over, replace
TPA, clean and pert fine At
1/2 Normal changes.

Quote

FrmREInquiry Repair Inquiry		الا	
Repair Number: RE00209231  Serial: E6338719 Model 700 3006 SPRG LH Produced: 01 /	Center Fre Labber   Repairman   Bluce Travis 07/1997 SKU 25913   Status   ApprovaHcld 11/4/2010 1:59:15 PM		,
ADDRESS INFORMATION			• • •
1285 4 300 3 7 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	inved from Return To CReceived from RICHARD EDINGER		
Name   RICHARD EDINGER	1605 LANE ROAD		
Address 2 PO Box	PO.Box		
Cay WATERFORD  State PA ZipCode 16441 County US	WATERFORD  PA Zip Code:   16441    Countily:   US		
A STATE OF THE PARTY OF THE PAR	FFE: C C C C C C C C C C C C C C C C C C C		
Contact / Condition   Problems   Estimate   History / Status   Shipping	/Billing		
Date Code LUse ID Desc1	Desc2   A   Shipping Hold   Current Status   Approval Hold   Approval Hold		
11/3/2010/22 New valentds Repair Added	Interface Hold   3174/2010 1:5915 PM		
11/3/2010 23 Update valentds Repair information of 11/3/2010 23 Update valentds Repair information of	Parts Received Repair Banch		
11/3/2010 2:3 Expedite valentds From Check In	To:   Passed Inspection   IUN		}
11/3/2010 23 Update valentds Repair information of	nange T Has Been Approved ILN	The state of the s	
4	► Internal Repair Trensler Number  □ Exclude TATC		
Repair Search	Refresh Close		
			f f
		32 50 1 2 A B	
A STATE OF THE STA	PART PRINTED AT SECTION	A CONTRACT OF THE STATE OF THE	
	and the same of th		
	The second secon		
•			



# BARBER - Kinzer PPS GAL RE 0010597 REMINGTON ARMS SERVICE Quotation

PO Box 700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

Madison, NC 27025-0700 www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL.

Repair Numbe RE00209231		erial Number / Description 6338719				eceived: te Date:	11/03/2 11/04/2	
	N	10del 700 Center Fire Caliber: 3006 SPRG LH			Date Pi	rinted:	11/08/2	010
Customer:				urn To:				
1605 LAN	EDINGER E ROAD ORD, PA 1644	21.11	RICHARD EDINGER 1605 LANE ROAD WATERFORD, PA 16441 US					
WAILIG	лю, т <i>т</i> точ-	03		WATERCORD	, IA 10441	03		
Please Circle C								
VISA M	C DISCOVE	R Card No PO Number:		Ex	p.Date			
Open Acco	unt. K	PO Nulliber.			•			
Approval Signa					_ Date:			
		Time to C						
If you de	sire any change	, please use the reverse side for your comments ar	nd mark this b	box.	water a management	11.7 4.25 - 6	* 1 4 7 1	an 100 / 1 12 / 12
Reported		Proble F	ns ound					
M100 - SEE	CUSTOMERS	LETTER   M	1123 - FOR	WARD TO PRO	DUCT SER	VICE FOR	INSPE	CTION
		ODUCT SERVICE FOR INSPECTION						
		OBOOT BERTICET ON HAD BOTTON						
		obect sex vice toking bellen						
( decorption of the decorption		Technition Co	omments 🎺					ing the control of th
ould not dupli	cate concern.ac	Technition Co	omments ce on bbl and	1 stock when rer	noved.check	over,replac	e trigger	plate assm
ould not dupli	cate concern.ac fire at 1/2 norm	Technition Cotion and trigger plate assm dirty. a white substantal charges.	ce on bbl and	i stock when rer	noved.check	over,replac	ce trigger	r plate assm
ould not dupli	cate concern.ac fire at 1/2 norm	Technition Co	ce on bbl and	i stock when rer	noved.check	over,replac	e trigger	plate assm
ould not dupliclean and test	cate concern ac fire at 1/2 norm  Type  Part	Technition Cotion and trigger plate assm dirty, a white substantal charges.  STIMATE (note: C.O.D./Shipping and Handlin Description  700 XMP EA TRIG ASSB RH BLACK (OS)	ng Charges: Qty Needed	are NOT Include Warranty  Billable	led in this ( Qty From Inv	Quote.) Price	Disc	Amount 57.50
ould not dupliclean and test Material F306371B	icate concern ac fire at 1/2 norm  Type  Part Service	Technition Contion and trigger plate assm dirty, a white substantal charges.  STIMATE (note: C.O.D./Shipping and Handlin Description  700 XMP EA TRIG ASSB RH BLACK (OS) GR-SHIPPING & HANDLING (GUN REPAI	ng Charges: Oty Needed 1 R) 1	are NOT Include Warranty  Billable Billable	ded in this C Qty From Inv 1	Quote.) Price 115.00 17.00	Disc 50	Amount 57.50 17.00
ould not dupliclean and test	cate concern ac fire at 1/2 norm  Type  Part	Technition Cotion and trigger plate assm dirty, a white substantal charges.  STIMATE (note: C.O.D./Shipping and Handlin Description  700 XMP EA TRIG ASSB RH BLACK (OS)	ng Charges: Qty Needed	are NOT Include Warranty  Billable	led in this ( Qty From Inv	Quote.) Price	Disc 50	Amount 57.50
ould not dupliclean and test Material F306371B	icate concern ac fire at 1/2 norm  Type  Part Service	Technition Contion and trigger plate assm dirty, a white substantal charges.  STIMATE (note: C.O.D./Shipping and Handlin Description  700 XMP EA TRIG ASSB RH BLACK (OS) GR-SHIPPING & HANDLING (GUN REPAI	ng Charges: Oty Needed 1 R) 1	are NOT Include Warranty  Billable Billable	ded in this C Qty From Inv 1	Quote.) Price 115.00 17.00	Disc 50	Amount 57.50 17.00
ould not dupliclean and test Material F306371B	icate concern ac fire at 1/2 norm  Type  Part Service	Technition Contion and trigger plate assm dirty, a white substantal charges.  STIMATE (note: C.O.D./Shipping and Handlin Description  700 XMP EA TRIG ASSB RH BLACK (OS) GR-SHIPPING & HANDLING (GUN REPAI	ng Charges: Oty Needed 1 R) 1	are NOT Include Warranty  Billable Billable	ded in this C Qty From Inv 1	Quote.) Price 115.00 17.00	Disc 50	Amount 57.50 17.00
ould not dupliclean and test Material F306371B	icate concern ac fire at 1/2 norm  Type  Part Service	Technition Contion and trigger plate assm dirty, a white substantal charges.  STIMATE (note: C.O.D./Shipping and Handlin Description  700 XMP EA TRIG ASSB RH BLACK (OS) GR-SHIPPING & HANDLING (GUN REPAI	ng Charges: Oty Needed 1 R) 1	are NOT Include Warranty  Billable Billable	ded in this C Qty From Inv 1	Quote.) Price 115.00 17.00	Disc 50	Amount 57.50 17.00
ould not dupliclean and test Material F306371B	icate concern ac fire at 1/2 norm  Type  Part Service	Technition Contion and trigger plate assm dirty, a white substantal charges.  STIMATE (note: C.O.D./Shipping and Handlin Description  700 XMP EA TRIG ASSB RH BLACK (OS) GR-SHIPPING & HANDLING (GUN REPAI	ng Charges: Oty Needed 1 R) 1	are NOT Include Warranty  Billable Billable	ded in this C Qty From Inv 1	Quote.) Price 115.00 17.00	Disc 50	Amount 57.50 17.00
ould not dupliclean and test Material F306371B	icate concern ac fire at 1/2 norm  Type  Part Service	Technition Contion and trigger plate assm dirty, a white substantal charges.  STIMATE (note: C.O.D./Shipping and Handlin Description  700 XMP EA TRIG ASSB RH BLACK (OS) GR-SHIPPING & HANDLING (GUN REPAI	ng Charges: Oty Needed 1 R) 1	are NOT Include Warranty  Billable Billable	ded in this C Qty From Inv 1	Quote.) Price 115.00 17.00	Disc 50	Amount 57.50 17.00
ould not dupliclean and test Material F306371B	icate concern ac fire at 1/2 norm  Type  Part Service	Technition Contion and trigger plate assm dirty, a white substantal charges.  STIMATE (note: C.O.D./Shipping and Handlin Description  700 XMP EA TRIG ASSB RH BLACK (OS) GR-SHIPPING & HANDLING (GUN REPAI	ng Charges: Oty Needed 1 R) 1	are NOT Include Warranty  Billable Billable	ded in this C Qty From Inv 1	Quote.) Price 115.00 17.00	Disc 50	Amount 57.50 17.00
ould not dupliclean and test Material F306371B	icate concern ac fire at 1/2 norm  Type  Part Service	Technition Contion and trigger plate assm dirty, a white substantal charges.  STIMATE (note: C.O.D./Shipping and Handlin Description  700 XMP EA TRIG ASSB RH BLACK (OS) GR-SHIPPING & HANDLING (GUN REPAI	ng Charges: Oty Needed 1 R) 1	are NOT Include Warranty  Billable Billable	ded in this C Qty From Inv 1	Quote.) Price 115.00 17.00	Disc 50	Amount 57.50 17.00
ould not dupliclean and test Material F306371B	icate concern ac fire at 1/2 norm  Type  Part Service	Technition Contion and trigger plate assm dirty, a white substantal charges.  STIMATE (note: C.O.D./Shipping and Handlin Description  700 XMP EA TRIG ASSB RH BLACK (OS) GR-SHIPPING & HANDLING (GUN REPAI	ng Charges: Oty Needed 1 R) 1	are NOT Include Warranty  Billable Billable	ded in this C Qty From Inv 1	Quote.) Price 115.00 17.00	Disc 50	Amount 57.50 17.00
ould not dupliclean and test Material F306371B	icate concern ac fire at 1/2 norm  Type  Part Service	Technition Contion and trigger plate assm dirty, a white substantal charges.  STIMATE (note: C.O.D./Shipping and Handlin Description  700 XMP EA TRIG ASSB RH BLACK (OS) GR-SHIPPING & HANDLING (GUN REPAI	ng Charges: Oty Needed 1 R) 1	are NOT Include Warranty  Billable Billable	ded in this C Qty From Inv 1	Quote.) Price 115.00 17.00	Disc 50	Amount 57.50 17.00
ould not dupliclean and test Material F306371B	icate concern ac fire at 1/2 norm  Type  Part Service	Technition Contion and trigger plate assm dirty, a white substantal charges.  STIMATE (note: C.O.D./Shipping and Handlin Description  700 XMP EA TRIG ASSB RH BLACK (OS) GR-SHIPPING & HANDLING (GUN REPAI	ng Charges: Oty Needed 1 R) 1	are NOT Include Warranty  Billable Billable	ded in this C Qty From Inv 1	Quote.) Price 115.00 17.00	Disc 50	Amount 57.50 17.00
ould not dupliclean and test Material F306371B	icate concern ac fire at 1/2 norm  Type  Part Service	Technition Contion and trigger plate assm dirty, a white substantal charges.  STIMATE (note: C.O.D./Shipping and Handlin Description  700 XMP EA TRIG ASSB RH BLACK (OS) GR-SHIPPING & HANDLING (GUN REPAI	ng Charges: Oty Needed 1 R) 1	are NOT Include Warranty  Billable Billable	ded in this C Qty From Inv 1	Quote.) Price 115.00 17.00	Disc 50	Amount 57.50 17.00
ould not dupliclean and test Material F306371B	icate concern ac fire at 1/2 norm  Type  Part Service	Technition Contion and trigger plate assm dirty, a white substantal charges.  STIMATE (note: C.O.D./Shipping and Handlin Description  700 XMP EA TRIG ASSB RH BLACK (OS) GR-SHIPPING & HANDLING (GUN REPAI	ng Charges: Oty Needed 1 R) 1	are NOT Include Warranty  Billable Billable	ded in this C Qty From Inv 1	Quote.) Price 115.00 17.00	Disc 50	Amount 57.50 17.00
ould not dupliclean and test Material F306371B	icate concern ac fire at 1/2 norm  Type  Part Service	Technition Contion and trigger plate assm dirty, a white substantal charges.  STIMATE (note: C.O.D./Shipping and Handlin Description  700 XMP EA TRIG ASSB RH BLACK (OS) GR-SHIPPING & HANDLING (GUN REPAI	ng Charges: Oty Needed 1 R) 1	are NOT Include Warranty  Billable Billable	ded in this C Qty From Inv 1	Quote.) Price 115.00 17.00	Disc 50	Amount 57.50 17.00

Sub Total:

Est Sales Tax:

86.00

5.16

# Mitchell, Christy

To:

Evans, Danny

Subject:

RE: A form was submitted on REMINGTON - PROD.

From: Evans, Danny

Sent: Wednesday, October 27, 2010 10:58 AM

**To:** Mitchell, Christy **Cc:** Loschin, John

Subject: FW: A form was submitted on REMINGTON - PROD.

Christy,

See note at bottom....FSR twice....please contact the customer today and provide direction.

Christy,

You might ask him how he attempted to e-mail us

John L.,

Did this one come into your area...claims to have e-mailed Rem with no response.

From: Roth, Fred

Sent: Wednesday, October 27, 2010 10:52 AM

To: Evans, Danny

Subject: FW: A form was submitted on REMINGTON - PROD.

see

**From:** Bill Powers [mailto:Bill-Powers@am.com] **Sent:** Wednesday, October 27, 2010 10:31 AM

To: Walter F. McLailen IV; Roth, Fred

Subject: FW: A form was submitted on REMINGTON - PROD.

From: forms@brandednews.com [mailto:forms@brandednews.com]

Sent: Wednesday, October 27, 2010 10:29 AM

To: Bill Powers

Subject: A form was submitted on REMINGTON - PROD.

Hello,

A form was submitted on the site. Please see submitted information below:

Form Title: Contact Us

First Name: richard

Last Name: edinger

Email: edinger3108@roadrunner.com

Address 1:

Address 2:

**Telephone: 814 796 6931** 

City:

State:

**Zip Code:** 16441

Country:

## Comments:

my model 700 30-06 has fired twice while i released the safety.can i send you this rifle for evaluation and repair.this is my second e-mail to remington without a response. i cannot sell,trade or give this rifle ti any person with this safety hazard.

Contact us on Repasite

Case#	4865	Date of Call	16/27/10	Date of a lincident		PreLit Lit	Obs (
Reporter name address contact #'s				Incident Name/Age address contact #'s	100 Wa	s Lane A Herford Pa	Ed. 4 16441
email		·		email			
Injury	recoil co	ut the	inb,	not b	rad		
Medical Treatment							
Alleged cause							
Firearm	Ser#	Cal	DOM	Orig owner?	When/W	nere purchased	
Ammunition	Factory/Reload	Manuf	Caliber	Bullet type/wgt	Lot#	Additional info	
Other Product						-	
	Jyrr. a  jt kined  Few w  put a  off s	leeks	t ritle	instra, Lou  puts  shi	took ght cope it be	he made in the hock	e the enor
Notes:							
Customer's Request	···						
My actions/	email 1	ARS -	- needs	· by e	erd	of Nov.	





Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

# ARS LABEL REQUEST FORM

DATE:	10/2//2010	REQUESTED BY:	christy	
QUANTITY:	1	WEIGHT PER PACKAGI	E:	10
PLEASE CHECK ONE				
MEDIA /	Email:			
COORDINATOR	edinger3108@roadrunner.c			
TO MAIL /		I WILL MAÍL		
DESCRIPTION:	<u> </u>			
	700			
	- Marie - Mari			
	<u> </u>			
	LABEL	. INF		
MAIL LABEL TO:	Richard Edinger	<del></del>		
	Email label to him			
		edinger3108(	@roadrunner.com	
	1605 Lane Rd			
	Waterford, Pa 16441			
	·			
RETURN ITEM TO	: Remington Product Service	e	<del>-</del>	
ļ	-			
1				

###