

CAL: 300 WIN MAG

PROJECT # 241314

BARBER - 5.22.06r0003597

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
SW/PR	12/19/02	Out of box Inspection	TLW1303A		
JS	12/22/03	De-torque Scope Cross Bolt	Front 30 in lb Rear 30 in lb		
BL	12/22/03	Head space	Min .002		
BL	12/22/03	Proof	Bolt light opening	1	1
BL	12/22/03	Head space	Min .002		
JS/BL	12/22/03	Depth front Take down Scope hole			
BL	12/23/03	Firing Pin Indent	would not take rusher holder for indents		
JS	12-29-03	Sear/Trigger Engagement	Arg. .0274		
JS	12-29-03	Sear lift	.0152		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Head space	Min +.005		
SW/JS	1/13/04	Proof RO		1	2
SW/JS	1/13/04	Head space after proof	Min +.005		
BL	1/15/04	200rd Basic Jack Funct test	magazine box hard to take out / Bolt hard to close	200	202
SW/BL	1/15/04	Head space	Min .005		
BL	1-16-04	Shoulder function test	X20 Rds.	20	222
JS/BL	1-19-04	Inspect & Clean	See Inspection sheet		

Logform

Confidential - Submitter ID: 221010003597 Order

ET19976

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-4

TLW #: TLW1303

Date: 01/19/04Inspector: JS/BLRound Level: 222
☒ Measure Headspace min + .005
☒ Sear Engagement: 1st. .02822 2nd. .0271 3rd. .0277
Ave. .0276 spec. .020" to .025"
☒ Trigger Pull: 1st. 4.576 2nd. 4.582 3rd. 4.247
Ave. 4.468 spec- 4 lb. to 5.5 lb.
☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive
wear: locking lugs some wear, excessive wear on bolt stop
☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of
note: insert has a defect must be in the mold.

TLW1303

Remington Confidential

ET19977