

CAL: 300 WIN MAG

PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START-0
				RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	TLW1303A		
JS	12-22-03	Detonate Scope Crosshair Screws	Front 25 Rear 30		
BL	12-22-03	Headspace	Min + .005		
BL	12-22-03	Proof	OK	1	1
BL	12-22-03	Headspace	Min + .005		
JS/BL	12-22-03	Depth Front Take down Screw hole			
BL	12-23-03	Firing Pin Indents	.020 - .022 - .020 Avg. .0206		
JS	12-29-03	Sear/Trigger Engagement	Avg. .0298		
JS	12-29-03	Sear lift	.017		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace Min + .006			
SW/JS	1/13/04	Proof & Rd		1	2
SW/JS	1/13/04	Headspace after proof Min + .006			
JS	1-14-04	200 Rd. Basic Jack function test	Bolt hard to close throughout test; Bolt hard to open rds. #181-200, Magazine was bent on front side	200	202
SW	1-15-04	Headspace Min + .006			
BL	1-16-04	Shoulder function test X20 Rds. shot fresh		20	222
JS/BL	1-19-04	Clean & Inspect	See Inspection Sheet		

Logform

BARBER - 5.22.06r0003617

Confidential - Submitter: 50.22.100.100 to 50.22.100.172 Order

ET19996

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-14

TLW #: TLW1303

Date: 01 / 19 / 04Inspector: JS/BLRound Level: 222☒ Measure Headspace mint .006☒ Sear Engagement: 1st. .0282 2nd. .0269 3rd. .0275Ave. .0275 spec. .020" to .025"☒ Trigger Pull: 1st. 4.785 2nd. 4.496 3rd. 5.360Ave. 4.880 spec. 4 lb. to 5.5 lb.☒ Check Take-Down Screws and Re-tighten if necessary.☒ Inspect extractor & bolt face area. Broken extractor☒ Inspect cam surface, locking lugs and bolt stop for signs of excessivewear: Locking lugs some wear - Bolt stop some wear☒ Inspect stock for any signs of cracking or other

failure.

☒ Other items ofnote: magazine box is protruding - receiver insert has a
defect must be on the mold.

TLW1303

Remington Confidential

ET19997