

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

BARBER - 5.22.06r0003619

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START-0
				RDS. FIRED	TOTAL RDS.
SW/PR	12/19/03	Out of box Inspection	TLW1203A		
JS	12-22-03	Detorque- Scope Crossbolt Screws	Front 27 Rear 25		
BL	12-22-03	Headspace min +.004			
BL	12-22-03	Proof OK		1	1
BL	12-22-03	Headspace min +.004			
JS/OL	12-22-03	Depth Front Take down Screw hole			
BL	12-23-03	Firing Pin Indents .019 - .021 Avg. .0193			
JS	12-29-03	Sear/Trigger Engagement Avg. .0291			
JS	12-29-03	Sear lift .0153			
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace Min +.007			
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Headspace after proof Min +.007			
JS	1-14-04	200 Rd Basic Jack Function test; Bolt hard to close thru out test, extremely hard on rds. 21-40 (had some brass for insp.)		200	202
		Hard to open bolt on rds. 181-200 F.T.E. X1			
		Hard to retract bolt over brass in mag. on first rd.			
		Magazine bent on front side			
SW	1-15-04	Headspace Min +.007			
BL	1-16-04	Shoulder Function test x 20 Rds. Bolt past Bolt Stop		20	222
JS/BL	1-19-04	Clean Inspert See Inspection Sheet Broken extractor			

Logform

Confidential - ~~Slender-3022060003195~~ Order
Williams v. Remington

ET1998

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A75

TLW #: TLW1303

Date: 01 1 19 104Inspector: JS/BL

Round Level: _____

- ☒ Measure Headspace min + .007
- ☒ Sear Engagement: 1st. .0282 2nd. .0265 3rd. .0275 Ave. .0274 spec. .020" to .025" .0245
Reset Trigg
- ☒ Trigger Pull: 1st. 4.139 2nd. 3.984 3rd. 3.736 Ave. 3.953 spec- 4 lb. to 5.5 lb. 4.616
Reset Trigg
- ☒ Check Take-Down Screws and Re-tighten if necessary.
- ☒ Inspect extractor & bolt face area. Broken extractor
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: BOLT STOP some wear Locking lugs some wear
- ☒ Inspect stock for any signs of cracking or other failure.
- ☒ Other items of note: magazine Box is protruding - receiver is bent has a defect must be in the mold.

TLW1303

Remington Confidential

ET19999