

GUN # A-18
 SERIAL # 71147113
 CAL: 300 WIN MAG

M/710 MAGNUM TRIAL PILOT TEST

TRACKING # TLW 1303
 PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS RDS. FIRED	AT START-0 TOTAL RDS.
SW/PR	12/19/03	Out of box Inspection	TLW1303A		
JS	12-22-03	Detorque-Scope Crossbolt screws Front Rear			
BL	12-22-03	Headspace	Min +.005		
BL	2-22-03	Proof	Ok	1	1
BL	12-22-03	Headspace	Min +.005		
JS/BL	12-22-03	Depth front Take down	New hole		
BL	12-23-03	Fire Pin Index	.021-.022-.022 Avg .0216		
JS	12-29-03	Seal/Trigger Engagement	Arg. .0274		
JS	12-29-03	Seal lift	.0145		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace Min +.006			
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Headspace after proof	Min +.006		
JS	1-15-04	200 Rd. Jack Function test	Bolt difficult to close throughout test, Rds 141-160 were difficult to chamber (soft point of round was flattening out from recoil flat end of ammo was difficult to slide over lip of magazine.) Front & Center Take down screws backed out, they were recovered and reinserted & torqued. RD.186	200	202
SW	1-15-04	Headspace Min +.007	Bolt hard to close / Bolt not functioning properly		
JS/BL	1-20-04	Clean/Inspect	See Inspection sheet Broken extractor	20	222

Logform

BARBER - 5.22.06P0003625

Confidential - SWARBER 1927060003625 Order

ET20004

Williams V. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-18

TLW #: TLW1303

Date: 01 19 104Inspector: JS/BCRound Level: 022☒ Measure Headspace min + .006☒ Sear Engagement: 1st. 0288 2nd. 0278 3rd. 026Ave. 0275 spec: 020" to 025"☒ Trigger Pull: 1st. 5.070 2nd. 4.700 3rd. 4.879Ave. 4.893 spec- 4 lb. to 5.5 lb.☒ Check Take-Down Screws and Re-tighten if necessary.☒ Inspect extractor & bolt face area. Broken extractor☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Bolt stop some wear☒ Inspect stock for any signs of cracking or other failure.☒ Other items ofnote: magazine Box protruding - receiver insert has defect must be the mold.

TLW1303

Remington Confidential

ET20005