

CAL: 300 WIN MAG

PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START-0
				RDS. FIRED	TOTAL RDS.
SW/PA	12/14/03	Out of box Inspection	TLW1702A		
JS	12-22-03	Detonator-Scope Crossbolt Screws	Front 30 Rear 32		
BL	12-22-03	Headspace	min + .005		
BL	12-22-03	Proof	Tight to open	1	1
BL	12-22-03	Headspace	min + .005		
JS/BL	12-22-03	Depth Front Takedown Screw hole			
BL	12-23-03	Firing Pin Indents	.022 - .027 - .021 Avg .0213		
JS	12-29-03	Sear/Trigger Engagement	Avg. .0272		
JS	12-29-03	Sear lift	.0148		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace Min + .006			
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Headspace after proof Min + .006			
JS	1-15-04	200 Rd. Jack function test	Bolt difficult to close on Rds. 81-100; 121-140; Not 180	200	202
SW	1-15-04	Headspace Min + .006	(Center Takedown screw loose)		
BL	1-16-04	Shoulder Fine	Bolt hard to close	20	222
JS/BL	1-20-04	Clean & Inspect	See Inspector sheet Broken extractor		

Logform

ET20006

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-19

TLW #: TLW1303

Date: 01 / 19 / 04

Inspector: JS/BL

Round Level: 222

☒ Measure Headspace min +006

☒ Sear Engagement: 1st. 0.0264 2nd. 0.0251 3rd. 0.0267

Ave. 0.026 spec. .020" to .025" 83

☒ Trigger Pull: 1st. 5.083 2nd. 4.691 3rd. 4.453

Ave. 4.742 spec. 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area. Broken extractor

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: Locking lugs some wear Bolt stop some wear

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: Magazine Box protruding

TLW1303

Remington Confidential

ET20007