

CAL: 300 WIN MAG

PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START-0
				RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	TLW1303A		
JS	12/22/03	De-torque Scope	Cross Bolt screws Front 30 Rear 30		
BL		Head space	Min +.005		
BL		Proof	Tight to open Emblem on bottom of stock fell off	1	1
BL	12/22/03	Head space	Min +.005		
JS/BL	12/22/03	Depth Front Take down Screw hole			
BL	12/23/03	Firing Pin Indents	.022-.022 .022 Aug .022		
JS	12-29-03	Sear/Trigger Engagement	Avg. .0259		
JS	12-29-03	Sear lift	.0178		
SW/JS	1/13/04	Change out bolt head			
SW/JS	1/13/04	Head space	Min +.006		
SW/JW	1/13/04	Proof Rd		1	2
SW/JW	1/13/04	Head space 25 ft proof	Min +.007		
B Lee	1/15/03	250rd JALC Fund test	magazine Box hard to take from magazine well / 11 FTE Bolt hard to rise	200	202
SW	1-15-03	Head space Min +.007	(Front Takedown screw loose)		
BL	1-16-04	Shoulder Fire	magazine came out / Bolt stop not functioning properly 1 FTE	20	222
JS/BL	1-20-04	Clean & Inspect	see Inspection sheet		

Logform

BARBER - 5.22.06r0003635

CONFIDENTIAL - SUPERSEDED BY ORDER 15.27.00

ET20014

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-23

TLW #: TLW1303

Date: 01 / 19 / 04Inspector: JS/BLRound Level: 222
☒ Measure Headspace min + .001
☒ Sear Engagement: 1st. 0.0231 2nd. 0.0233 3rd. 0.0231
Ave. 0.0231 spec. .020" to .025"
☒ Trigger Pull: 1st. 5.042 2nd. 5.177 3rd. 5.070
Ave. 5.096 spec- 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Bolt stop worn
☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of
note: magazine Box protruding

TLW1303

Remington Confidential

ET20015