

CAL: 300 WIN MAG

PROJECT # 241314

BARBER - 5.22.06r0003739

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START-0
				RDS. FIRED	TOTAL RDS.
SW/PR	12/19/03	Out of box Inspection	TLW 1203A		
JS	12/22/03	De-torque Scope Cross Bolt Screw Front 20in Lb Rear 25in Lb			
BL	12/22/03	Headspace Min + .002			
BL	12/22/03	Proof Tight opening Bolt		1	1
BL	12/22/03	Headspace Min + .002			
JS/BL	12/22/03	Depth Front Take down renew bolt			
BL	12/22/03	Firing Pin Indents 1020 - 2070 - 020 Aug. 0196			
JS	12-29-03	Scot/Trigger Engagement Avg. 0274			
JS	12-29-03	Sear lift 0152			
SV/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace Min + .003			
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Headspace after proof Min + .004			
Sw	1/14/04	300 Rd Basic Jack Function Test		200	202
SW/JS	1/15/04	Headspace Min + .004			
B.L.	1-16-04	Shoulder function test X20 Rds. Shot clean		20	222
JS/BL	1-19-04	Inspect & clean See Inspection sheet			

Logform

Confidential - Submitter 5.28.06#0003799 Order

ET20118

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-6

TLW #: TLW1303

Date: 01 / 19 / 04Inspector: JS/BLRound Level: 222

- ☒ Measure Headspace min+.004
- ☒ Sear Engagement: 1st. .0267 2nd. .026 3rd. .0268 Ave. .0265 spec- .020" to .025" ⁸³
- ☒ Trigger Pull: 1st. 4.966 2nd. 4.841 3rd. 4.963 Ave. 4.857 spec- 4 lb. to 5.5 lb.
- ☒ Check Take-Down Screws and Re-tighten if necessary.
- ☒ Inspect extractor & bolt face area.
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Bolt stop worn, some wear on locking lugs
- ☒ Inspect stock for any signs of cracking or other failure.
- ☒ Other items of note: magazine Box protruding, receiver insert has a defect must be on the model

TLW1303

Remington Confidential

ET20119