

GUN # A-15

SERIAL # 71147093

CAL: 300 WIN MAG

M/710 MAGNUM TRIAL PILOT TEST

TRACKING # TLW 1303

PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
SW/PIR	12/19/03	Out of box Inspection	TLW1303A		
JS	12-22-03	Detorque- Scope Crosshairs	Front 27 Rear 25		
BL	12-22-03	Headspace	Min + .004		
BL	12-22-03	Proof	OK	1	1
BL	12-22-03	Headspace	Min + .004		
JS/BL	12-22-03	Depth Front Take down Scope hole			
BL	12-23-03	Firing Pin Index	.019 - .018 .021 Avg. .0193		
JS	12-29-03	Sear/Trigger Engagement	Avg. .0291		
JS	12-29-03	Sear lift	.0153		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace	Min + .007		
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Headspace after proof	Min + .007		
JS	1-14-04	200 Rd Basic Jack Function test	Bolt hard to close throughout test, extremely hard on rds 21-40 (brass for insp.)	200	202
			Hard to open bolt on rds 181-200 F.T.E. X1		
			Had to retract Bolt over brass in mag. on first rd.		
			Magazine bent on front side		
SW	1-15-04	Headspace	Min + .007		
BL	1-16-04	Shoulder Function test	x20 Rds. Bolt past bolt stop	20	222
JS/BL	1-19-04	Clean & Inspect	See Inspection Sheet Broken extractor		

Logform

BARBER - 5.22.06-0003757

Confidential - Submitter to 2206 Remington Order Williams v. Remington

ET20136

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A75

TLW #: TLW1303

Date: 01 1 19 1 04Inspector: JS/BL

Round Level: _____

☒ Measure Headspace min + .002☒ Sear Engagement: 1st. .0282 2nd. .0265 3rd. .0275Ave. .0274 spec. .020" to .025"☒ Trigger Pull: 1st. 4.139 2nd. 3.984 3rd. 3.736Ave. 3.953 spec. 4 lb. to 5.5 lb.☒ Check Take-Down Screws and Re-tighten if necessary☒ Inspect extractor & bolt face area. Broken extractor☒ Inspect cam surface, locking lugs and bolt stop for signs of excessivewear: BOLT STOP some wear, Locking lugs some wear☒ Inspect stock for any signs of cracking or other failure.☒ Other items ofnote: magazine Box is protruding - receiver insert has a defect must be in the mold.

TLW1303

Remington Confidential

ET20137