

GUN # A-18

SERIAL # 71147113

CAL: 300 WIN MAG

M/710 MAGNUM TRIAL PILOT TEST

TRACKING # TLW 1303

PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
SW/PR	12/19/03	Out of box inspection	TLW1303A		
JS	12-22-03	Detorque-Scope Crossbolt Screws Front Rear			
BL	12-22-03	Headspace	min +.005		
BL	12-22-03	Proof	Ok.	1	1
BL	12-22-03	Headspace	min +.005		
JS/BL	12-22-03	Depth Front Take down Screw hole			
BL	12-23-03	Firing Pin Indent	.021-.0032 Avg. .0216		
JS	12-29-03	Sear/Trigger Engagement	Avg. .0274		
JS	12-29-03	Sear lift	.0145		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace Min +.006			
SW/JS	1/13/04	Proof & Rd		1	2
SW/JS	1/13/04	Headspace after proof	Min +.006		
JS	1-15-04	200 Rd. Jack Function test	Bolt difficult to close throughout test, Rds 141-160 were difficult to chamber (soft point of round was flattening out from recoil Flat end of ammo was difficult to slide over lip of magazine.) Front & Center Take down screws backed out, they were recovered and reinserted & torqued.	200	202
SW	1-15-04	Headspace Min +.007			
			Bolt hard to close, Bolt not functioning properly		
JS/BL	1-20-04	Clean & Inspect	see inspection sheet Broken extractor	20	222

Logform

BARBER - 5.22.06/0003763

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-18

TLW #: TLW1303

Date: 01 1 19 104Inspector: JS/BLRound Level: 222☒ Measure Headspace min + .006☒ Sear Engagement: 1st. 0288 2nd. 0278 3rd. 026Ave. 0275 spec. .020" to .025" Posit 33.18☒ Trigger Pull: 1st. 5.070 2nd. 4.700 3rd. 4.879Ave. 4.883 spec- 4 lb. to 5.5 lb.☒ Check Take-Down Screws and Re-tighten if necessary.☒ Inspect extractor & bolt face area. Broken extractor☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Bolt stop some wear☒ Inspect stock for any signs of cracking or other failure.☒ Other items ofnote: magazine Box protruding - receiver insert has defect must be the mold.

TLW1303

Remington Confidential

ET20143