

CAL: 300 WIN MAG

PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START-0
				RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	TLW1303A		
JS	12/22/03	De-Torque Scope	Front 35 Rear 35		
BL	1	Head Space	min +.003		
BL	1	Proof	OK	1	1
BL	12/22/03	Head Space	min +.003		
JS/BL	12/22/03	Depth Front Takedown Screw hole			
BL	12/23/03	Firing Pin Indent	.019 .020 - .020 Avg .0196		
JS	12-29-03	Gear/Trigger Engagement	Arg. .031		
JS	12-29-03	Gear lift	.0158		
SW/JS	1/13/04	Change out bolt head			
SW/JS	1/13/04	Head space	Min +.005		
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Head space after proof	Min +.005		
SW	1/15/04	200 Rd Basic Jmk Function Test		200	202
SW	1-15-04	Head space - Min +.005	(Front & Center Takedown screw loose)		
BL	1-16-04	Shoulder Fire	Bolt stop not functioning properly / 1 FT Feed	20	222
			1 FTE		
JS/BL	1-20-04	Clean & Inspect	See Inspection sheet		

Logform

ET20160

CONFIDENTIAL

Remington Arms Company/Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-28

TLW #: TLW1303

Date: 01/20/04

Inspector: JS/BL

Round Level: 222

☒ Measure Headspace min. .005

☒ Sear Engagement: 1st. 030 2nd. 030 23rd. 0302

Ave. 0301 spec. .020" to .025"

☒ Trigger Pull: 1st. 4.594 2nd. 5.341 3rd. 5.469

Ave. 5.136 spec- 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area. Some wear on bolt face

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: Locking lugs some wear bolt stop worn

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: magazine box protruding

TLW1303

Remington Confidential

ET20161