

after tests on 11-15-65

Difl 139413.

5200 can surface that contacts firing pin head
can surface. Shiny spots showing which means
some wear but not excessive. Corrosion in some
places.



in contact on flat surface. very
light.

5200 surface that contacts connector surface. with
oil on surface it looks like a deposit of rust. when
oil is removed it looks clean & shiny.

connector surface with oil on it looks as though it
has a varnish or rust film. when oil is removed
the surface was shiny & shows the surface that
it is in contact with the 5200.




Difl 139555

5200 can surface same as above



5200 surface that contacts connector same as above.

connector surface same as above except that when
oil is removed there are still some spots that look like
varnish or rust.



prints show
marks