

COMMENTS FROM TECHNICIANS:
STROOK TAKE DOWN DEVICES ARE NOT TIGHTENED TO TORQUE SPEC SOME ARE BARELY POSITIONED AT ALL
STROKE LONG IT NEEDS NOT BEARINGS ARE NOT TIGHT