

II. Remington M700 (ADL-BDL)Wood

- All bolt handle cuts are rough, full of debris and poorly finished.
- Crushed checkering on the right side of a pistol grip on one ADL rifle.
- Finish and wood is chipping away on some of the stocks, primarily around the grip caps and where the sling strap screws are located.
- All the brass stock reinforcement pins are eggshaped.
- Small dents and scratches were recorded on three of the rifles (superficial).
- All of the stocks have a nice glossy finish.
- Good inletting of the stocks to the barrels.

Metal

- Poor polish and color on all the bolt plugs.
- Polishing marks are evident on all the barrels.
- Two barrels have traces of GFM hammer marks on them.
- Poor color on all the recoil lugs. They look dull compared to the barrel and receiver finishes.
- Poor color on all the sight bases. They also have a "rough finish" look to them.
- Good polish and color on the floor plates and trigger guards.

Ruger M77Wood

- The fore end tip of the varmint rifle is cracked 3".
- Heavy scratches were found on three stocks.
- All bolt handle cuts have torn grain, wood burns, and gouging.
- Poor fill and stain on all stocks.
- Two rifles have a white plastic strand hanging out from the insert on the grip cap.
- The recoil pads do not fit tight to the stocks on some of the rifles (gaps).
- Good inletting for barrel fit.

Metal

- Rust pits were found on some of the bolts, barrels and receivers.
- A deep  $\frac{1}{4}$ " scratch, 6" from the muzzle end on one rifle.
- The finish is wearing off on two receivers at the tang area near the safety switches.
- Polishing marks are noticeable the full length of the barrels.
- Poor finish on the trigger guards and floor plates - very dull; doesn't match the receiver and barrel.