

RECEIVING and ESTIMATE REPORT

ORDER R **22286**

PROV DATE 11/14/76 RECEIVED 9176 ESTIMATED up VIA W33 CHARGES

FROM Peoria Police Dept

542 SW Adams St Peoria, ILL

MODEL and GRADE 700 BDL variant 223cm SERIAL NO. H6231124 DATE CODE X2

GRADE CODE 12/15

FOR COMPUTER REFER. ONLY Lights REPAIR CHG. 80 55

INS.

PARCEL POST

GUN CONDITION (New) (Slightly worn) (Very worn) (Misused) (Quoted) TOTAL

CUSTOMER'S COMPLAINT Safety moved from safe to fire

Position & he wrapped in fire.

MAIN FAULT Trigger connector Broken

GALLERY REPORT 19461 - trigger connector

File - M/700 Customer Complaints

Done

PLAINTIFF'S EXHIBIT
3169

173
AL 0029689

RECEIVING and ESTIMATE REPORT

ORDER R 22285

FROM DATE

7-14-76

ESTIMATED

9/27

VIA

up

CHARGES

FROM

Peoria Police Dept

TO

SW Adams St Peoria, ILL

MODEL and GRADE

700BOLynen at 223 Rem

SERIAL NO.

AL36452

DATE

XZ

CODE

2/15

FOR COMPUTER REFER. ONLY

L1 Slight

REPAIR CHG.

80.55

INS.

PARCEL POST

GUN CONDITION (New) (Slightly worn) (Very worn) (Misused) (Ruined)

TOTAL

CUSTOMER'S COMPLAINT

Safety ~~not~~ safe to fire
position & he was ~~not~~ ready to fire

MAIN FAULT

gun water Broken Trigger ADS
surrounds not properly ADS outside factory

GALLERY REPORT

19461 - Trigger gun water

7-14-76
Customer Complaints

ADS Trigger (H)

(Clean) (Test) (Target)

Inspection

223
AL 0029690

POLICE DEPARTMENT

CITY OF
PEORIA

Sept. 3, 1976

Remington Arms

Arms Service Division

Elion, N.Y. 13357

Gentlemen:

Enclosed please find two Remingtons, Model 700, Varmint Special, .223 Cal.
rifles- Serial #'s A6237966 and A6236452. R 22285

These rifles were purchased by this department earlier this year from
Varmes Guns Inc., Belle Fontaine, Ohio. Both of these weapons were found
defective and when we contacted them, we were informed to send them
back to the manufacture as they would be the only ones who would repair
them.

Both these weapons are used by our Tactical Unit, and we are in need
as soon as possible.

Both of these weapons were fired less than 100 rounds when it was found that
they were unsafe. With a live round in the chamber and the bolt closed, the
safety was moved from the "safe" to "fire" position the weapon would fire.
This did not happen every time, but it did happen intermittently.

Sincerely,

Sergeant Russell Davis

5425th Admin
Rec'd: 10/15/1907
300/672-1521

AL 0029691
393