- John T wanted to know why we would adjust or replace. Tom advised that if the
  sear was tampered with we would replace for safety reasons. John T. asked about
  if the screws were adjusted. He advised the team that this was all reviewed with
  the "lawyers" and they were ok with sending the customers trigger back.
- Bob L. and Fred advised that what they recall from the trigger meetings was that
  we have no right to keep a customers trigger and that the trigger would be sent
  back with a warning after the customer had completed the appropriate
  documentation.
- John T asked if we follow safe gun handling procedures it should not matter about the trigger pull. John T asked if the gallery would fail a firearm for the trigger pull. Chris advised that we need a written policy.
- Bob L. asked for written documentation that the firearms could go out with adjusted triggers. Danny Evans is going to follow up with Dale Wills and advise the team of his findings.
- Steve advised that they are watching for Model 700's that fail to extract. These
  were mainly magnums.

## **Model 870:**

- Ken spoke about 870 extractors. Over 2,000 have been replaced or sold for the 2004 year. Over 4,000 went to Law Enforcement.
- Greg advised that there was a problem back in 2001 & 2002, some or most of these guns might be from this timeframe. Grey has not heard of any new problems.
- Bob O advised that he has not seen any fails to feed issues. Ken has previously talked about the possibility of the fore-end getting torqued causing the shell or feel latch failing to come back.
- Bob O will look for possible under sizing of action bars.
- John L. asked about the discoloration of the barrel guide ring on the LE barrels.
   Boh O. and Greg advised that this was resolved over the summer of 2004. Bob L.
   tooked for examples in his parts crib but was not able to provide any.

