

**Accuracy Received:**

- 3 < 1"
- 9 1" – 1.5"
- 1 2" – 2.5"

**Accuracy Returned:**

- 3 < 1"
- 10 1" – 1.5"

- Chris is concerned that we are not seeing many guns come in for accuracy. The team discussed it and decided to discontinue reporting accuracy information. We will still make ourselves aware of concerns but need to concentrate our efforts on other issues.
- Ken advised that he is having two guns come in for accuracy evaluation.
- Bob L. requested we rerun our quality code report to determine what our number one concern is.
- Steve advised that they are still gathering accurizing information. They are currently gathering information on 14 varmint SKU's. He also advised that they are accurizing 100% of five SKU's.
- Chris advised that they are three shot groups.
- John L asked about the repair process on the new XCR finish. Steve advised that to refinish the firearm will be more difficult than a normal finish. They will be determining what process it will take to remove the old finish.
- Bob L asked about the refinish process for the VSSFII with the blued flutes. Steve advised that to refinish this model they would have to re-blue the entire gun then polish around the flutes.
- Danny requested an updated list of gallery ammo used for testing and targeting.
- Steve asked Andy Longway to provide Danny with the gallery target and testing specs spreadsheet.

**Model 332:**

- Bob O. advised that they he received four Model 332's back for evaluation.
  - 1 had a broken stock
  - 1 had a bulge on the barrel near the choke tube (concentricity).
  - 1 loose fore-end and second barrel would not fire
  - 1 not fitted correctly, space between frame.