

MODEL
700

DATE OF CALL BACKS

Aug. 7th To Aug. 15th '90

PROBLEMS

The firing pin head had a below Spec. heat treatment. Premature wear may show in this part, which could eventually cause harder than normal bolt lift, and in time could lead to an accidental firing.

Return to: Remington Arms Co., Inc.
Attn: Dept. FP
Ilion, NY 13357

July 1987 to Dec. 1987

Trigger connectors were re-bent after they were heat treated because of this change the possibility of connector breakage was introduced.

Return to: Remington Arms Co., Inc.
14 Hoefler Ave.
Ilion, NY 13357

Dec. 1993 to Jan 1994

One of the parts in the trigger assem. may be out of specifications.

Return to: Remington Arms Co., Inc.
14 Hoefler Ave.
Ilion, NY 13357

Jan. to March 1990

The sear safety cam in a limited quantity of rifles made between March 6th 1990 and Jan. 10th '90 may have been softer than our specification. The "soft" part may show premature wear and may eventually cause harder than normal safety switch force. Return to:
Remington Arms Co., Inc.