

Item #	Date Added	Priority	Model	Problem	Frequency of Complaint	Investigation Assignment	Investigation Completion Date	Investigation Status	Corrective Action	Corrective Action Responsibility
1	20-Apr	1	700	failing to extract	3 calls in one week 5/29- Still problem in Arm repair.	Joe Diliberto, Torn to save examples for Stuart.			Increasing the number of 338 UM in weekly audit. Arm has been polishing the chambers and blending the extractors.	
2		1	700 338UM/ 300UM	lands not reaching the chamber.	2 Rifles one repair s/n S6361331, and S6361915.			Checking the production spec.	New spec for the free-bore to be opened (increase the Die.)	
3		3	700 300um	shaving brass at the bolt face	repairman noticed more than usual in for repair. 9477,9706					
4	Sep. 20	3	700	ISS Firing pin sticking if ISS is in the wrong spot.	John Trull to explain.	Stuart, Fond that if the ISS is not moved all the way to fire it will prevent the firing pin from moving.		Dennis, Testing		

~AUTODATE

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0003311

MAE000003227