

Based on the serial number that I have provided, I'm sure your records indicate that this Model 700 was made in either 1969 or 1970 and it was purchased by my father probably between 1970 and 1972 at a local gun shop.

I've also had problems with the trigger mechanism while shooting the rifle. When shooting the rifle, the cartridge fires a 1/2 second later after the trigger pull. This has happened several times and cost me a deer one year. I of course have taken it to several gunsmiths in the past to work on the trigger and have it thoroughly cleaned. I also have cleaned the rifle regularly after shooting it. By the way, it's happen with both your ammunition and other premium ammunition. I don't think it's the ammo.

What concerns me is you never know when this is going to happen. Nevertheless, it happens enough for you to remember the incident. This is obviously a safety concern and one that needs to be fixed immediately without additional publicity. You see a hunter, firearms owner, and NRA member, the last thing I want to read about is negligence or lack of concern on the part of the firearms industry and Remington in particular.

Please advise me what the next course of action is. What can you tell me that will correct this problem? I look forward to your response. Thank you for your attention in this matter.

Respectfully,

George A. Gomez