

GUN # A-15

M710 MAGNUM TRIAL PILOT TEST

TRACKING # TLW 1303

PROJECT # 241314

SERIAL # 71147093

CAL: 300 WIN MAG

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	TLW1303A		
JS	12-22-03	Detorque Scope Crosshairs	Front 27 Rear 25		
BL	12-22-03	Headspace Min + .004		1	1
BL	12-22-03	Proof OK			
BL	12-22-03	Headspace Min + .004			
JS/BL	12-22-03	Depth Front Take down Screw hole			
BL	12-23-03	Firing Pin Index .019 - .018 .021 Avg. .0193			
JS	12-29-03	Sear/Trigger Engagement Avg. .0291			
JS	12-29-03	Sear lift .0153			
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace Min + .007		1	2
SW/JS	1/13/04	Proof Rd			
SW/JS	1/13/04	Headspace after proof Min + .007			
JS	1-14-04	200 Rd Basic Jack Function test; Bolt hard to close throughout test extremely hard on rds 21-40 kept using brass for insp.		200	202
		Hard to open bolt on rds 181-200 FTE X1			
		Hard to retract Bolt over brass in mag. on first rd.			
		Magazine bent on front side			
SW	1-15-04	Headspace Min + .007			
BL	1-16-04	Shoulder function test x20 Rds. Bolt past bolt stop		20	222
JS/BL	1-19-04	Clean & Inspect See Inspection Sheet Broken extractor			

Logform

85

ET20136

Confidential - Subject to Protective Order

Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A75

TLW #: TLW1303

Date: 01 / 19 / 04

Inspector: JS/BL

Round Level: _____

☒ Measure Headspace min + .007

☒ Sear Engagement: 1st. 0.282 2nd. 0.265 3rd. 0.275

Ave. 0.274 spec. .020" to .025"

☒ Trigger Pull: 1st. 4.139 2nd. 3.984 3rd. 3.736

Ave. 3.953 spec. 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary

☒ Inspect extractor & bolt face area. Protruding extractor

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: BOLT STOP SOME WEAR LOCKING LUGS SOME WEAR

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: magazine Box is protruding - receiver is bent has a defect must be in the mold.

TLW1303

Remington Confidential

ET20137