

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

CAL. 500 WIN MAG				ROUNDS AT START-0	
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	TLW 1303		
JS	12/22/03	De-Torque Scope	Cross Bolt screws Front 25 Rear 25		
BL		Head space	Min + .005		
BL		Proof	OK	1	1
BL	12/22/03	Head space	Min + .005		
JS/BL	12/22/03	Depth Front Take down	Screw hole		
BL	12/23/03	Firing Pin Ident.	.021 - .022 Avg .0213		
JS	12-29-03	Sear/Trigger Engagement	Arg. .0182		
JS	12-29-03	Sear 1/4"	.0166		
SW/JS	1/13/04	Change out bolt head			
SW/JS	1/13/04	Head space	Min + .006	1	2
SW/JS	1/13/04	Proof Rd			
SW/JS	1/13/04	Head space after proof	Min + .007		
BL	1/15/04	200rd Facb Funct. test	Magazine Box hard to cone from magazine well / 4 FTE Bolt hard to close	200	202
SW	1-15-04	Head space Min + .007	(Front Take down screw loose)		
BL	1-16-04	Shoulder Fine	Bolt hard to close / 1 FTE	20	222
JS/BL	1-20-04	Clean & Inspect	See Inspection Sheet		

Logform

Qa

Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-22

TLW #: TLW1303

Date: 01 / 19 / 04

Inspector: JS/BL

Round Level: 222

☒ Measure Headspace min + .007

☒ Sear Engagement: 1st. 0264 2nd. 0268 3rd. 0256

Ave. 0262 spec. .020" to .025" 83

☐ Trigger Pull: 1st. 4.920 2nd. 5.328 3rd. 5.244

Ave. 5.264 spec- 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area. Broken extractor

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: Locking lugs some wear, Bolt stop some wear

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: magazine Box protruding

TLW1303

Remington Confidential

ET20150