

CAL: 300 WIN MAG

M710 MAGNUM TRIAL AND PILOT TEST 1.1

TRACKING # TLW 1407
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
JW/BL	2/16/2004	OUT OF BOX	INSPECTION OK		
SW/BL	2/16/2004	HEADSPACE BEFORE	PROOF MIN + .005		
SW/BL	2/16/2004	PROOF ROUND		1	1
SW/BL	2/16/2004	HEADSPACE AFTER	PROOF MIN + .005		
SW/JW/BL	2/16/04	INDENTS			
SW/BL	2/17/04	SEAR LIFT	SEE DATA SHEET		
SW/BL	2/17/04	ENGAGEMENT	↓ ↓ ↓		
SW/BL	2/17/04	TRIGGER PULL			
BL	2/19/04	200rd JACK Funct.		200	201
BL	2/24/04	500rd Ext. Endur Test		500	201
BL	3/8/04	Clean/Inspection	See Inspection Sheet		

Logform

ET21096

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-15

TLW #: TLW1303

Date: 3 / 8 / 04

Inspector: BL

Round Level: 701

- ☒ Measure Headspace min+.005
- ☒ Inspect Take Down Screws for loosening. Top screw 1/2 turn - Center screw 1/4 turn 83
- ☒ Sear Engagement: 1st. .0349 2nd. .038 3rd. .0342 Ave. .0343 spec. .025" to .030"
- ☒ Reset Sear Engagement if Required: 1st. .0295 2nd. .0290 3rd. .0294 Ave. .0293
- ☐ Trigger Pull: 1st. 5.285 2nd. 5.428 3rd. 5.342 Ave. 5.352 spec- 4.5 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st. 2nd. 3rd. Ave.
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: cam surface, locking lugs, some sign of wear
bolt stop excessive wear
- ☒ Inspect stock for any signs of cracking or other failure: cracked stock at center screw hole

☐ Other items of
note:

TLW1216

Remington Confidential

ET21097