```
Firing Pin Indent- complete
>*
        Bolt Stop function test- complete
        10 rd. safety function- complete, A-14 would not fire twice during this test, looks like follow
downs. Details on sheet in packet. (with gun in my office)
        Bore Sighting check on A-21 to A-30 complete, less A-26
        All scopes have been removed in preparation for further testing.
>The firing pin head to sear engagement is next, then come accuracy, $90 rd function & detailed
> I thought we want to have a sit down and discuss what we've seen to this point before continuing into
function & accuracy.
>PKR
>
>
        From: Franz, Scott
        Sent:
                Saturday, November 04, 2000 2:17 PM
                Reesor, Phillip K.; Danner, Dale
        To:
                Snedeker, Jim; Diaz, Danny; Keeney, Mike; Franz, Scott
        Cc:
        Subject:
                        T & P Status for Saturday
        Importance:
                        High
        Labeled 30 guns A-1 to A-30
        Inspected all 30 guns for Magnaflux and Proof marks - OK
        Measured headspace as received
                        1. Gun A-2 (71001425) Can't close on min gauge plug (closes on dummy rd),
                           tagged gun. Gun is out of test for now. Can take measurements but do not
shoot until we all review.
        Ran 10 rd. Safety Function Test w/Lanyard on guns A-21 to A-30 only.
>*
>
                         1. Gun A-26 taken out of test 3rd rd. failed to fire (possible follow down) and
                           4th rd. fired when bolt was being rotated into the closed position(was fully
locked when it fired).
                           Note: Safety was off during the 10 rd. test as per my instructions.>
                           Measured trigger pull and engagement and then put in my office.
>
        Measured trigger pull on gurs A-1 to A-20
>1
        Measured Indent on guns A-1 to A-20
                        1. During this the bott stop on gun A-15 (71001464) broke. Broken piece in bag
                                manformation pouch. The first indent was taken ok. While closing the
bolt to take the second indent the bolt would not close. When the bolt was opened a small metal piece
fell out of the gun. At this time it was noticed that the bolt stop was broken. Tagged gun. Out of test for
now.
        Performed Bolt Stop Function Check on guns A-1 to A-20. Did not measure forces yet. Need to
come up with a way to do this. Guys mentioned that the bolt stop functioning gets easier as it is cycled,
even after only a few cycles
        >As far as Sunday activity would just continue with the preliminary measurements on guns A-1
to A-20. After this you could do the Bore Sight Test on guns A-21 - A-30 (minus A-26). Do not adjust
scope at any time, just smoot one 5-shot group using the same POA and save targets for measurement
later. After the bore sight test you could do Preliminary measurements on these 10 guns to catch them
up with the other 20. Call if you have any questions.
>
>
        Scott
>
```