

Phillip Reesor

From: Reesor, Phillip K.
Sent: 11/05/2000 11:50:29 AM
To: Danner, Dale; Franz, Scott
CC: Snedeker, Jim; Diaz, Danny; Keeney, Mike
BCC:
Subject: RE: T & P Status for Saturday & Sunday

Sunday: worked 6:00 to 12:00
 Trigger pull- complete
 Firing Pin Indent- complete
 Bolt Stop function test- complete
 10 rd. safety function- complete, A-14 would not fire twice during this test, looks like follow downs.
 Details on sheet in packet. (with gun in my office)
 Bore Sighting check on A-21 to A-30 complete, less A-26
 All scopes have been removed in preparation for further testing.
 The firing pin head to sear engagement is next, then come accuracy 100 rd function & detailed measurements.
 I thought we want to have a sit down and discuss what we've seen to this point before continuing into function & accuracy.

PKR

From: Franz, Scott
Sent: Saturday, November 04, 2000 2:17 PM
To: Reesor, Phillip K.; Danner, Dale
Cc: Snedeker, Jim; Diaz, Danny; Keeney, Mike; Franz, Scott
Subject: T & P Status for Saturday
Importance: High

Labeled 30 guns A-1 to A-30

Inspected all 30 guns for Magnaflux and Proof marks - OK

Measured headspace as received

1. Gun A-2 (71001425) : Can't close on min. gauge plug (closes on dummy rd).
 tagged gun. Gun is out of test for now. Can take measurements but do not shoot until we all review.

Ran 10 rd. Safety Function Test w/ Lanyard on guns A-21 to A-30 only.

1. Gun A-26 taken out of test. 3rd rd. failed to fire (possible follow down) and
 4th rd. fired when bolt was being rotated into the closed position (was fully locked when it fired).

Note: Safety was off during the 10 rd. test as per my instructions.

Measured trigger pull and engagement and then put in my office.

Measured trigger pull on guns A-1 to A-20.

Measured Indent on guns A-1 to A-20.

1. During this the bolt stop on gun A-15 (71001464) broke. Broken piece in bag
 in information pouch. The first indent was taken ok. While closing the bolt to take the second indent the
 bolt would not close. When the bolt was opened a small metal piece fell out of the gun. At this time it
 was noticed that the bolt stop was broken. Tagged gun. Out of test for now.

Performed Bolt Stop Function Check on guns A-1 to A-20. Did not measure forces yet. Need to come
 up with a way to do this. Guys mentioned that the bolt stop functioning gets easier as it is cycled, even
 after only a few cycles

Subject to Protective Order - Williams v. Remington