

Dale Danner

From: Reesor, Phillip K.
 Sent: 11/05/2000 11:45:51 AM
 To: Danner, Dale; Franz, Scott
 CC: Snedeker, Jim; Diaz, Danny; Keeney, Mike
 BCC:
 Subject: RE: T & P Status for Saturday & Sunday

Sunday: worked 6:00 to 12:00

- * Trigger pull- complete
- * Firing Pin Indent- complete
- * Bolt Stop function test- complete
- * 10 rd. safety function- complete, A-14 would not fire twice during this test, looks like follow downs. Details on sheet in packet. (with gun in my office)

* Bore Sighting check on A-21 to A-30 complete, less A-26

* All scopes have been removed in preparation for further testing.

The firing pin head to sear engagement is next, then come accuracy 100 rd function & detailed measurements.

I thought we want to have a sit down and discuss what we've seen to this point before continuing into function & accuracy.

PKR

>-----

>From: Franz, Scott
 >Sent: Saturday, November 04, 2000 2:17 PM
 >To: Reesor, Phillip K.; Danner, Dale
 >Cc: Snedeker, Jim; Diaz, Danny; Keeney, Mike; Franz, Scott
 >Subject: T & P Status for Saturday
 >Importance: High

>
 >* Labeled 30 guns A-1 to A-30
 >
 >* Inspected all 30 guns for Magnaflux and Proof marks - OK
 >
 >* Measured headspace as received
 > 1. Gun A-2 (71001425) : Can't close on min. gauge plug (closes on dummy rd),
 > tagged gun. Gun is out of test for now. Can take measurements but do not shoot
 > until we all review.

>
 >* Ran 10 rd. Safety Function Test w/ Lanyard on guns A-21 to A-30 only.
 > 1. Gun A-26 taken out of test, 3rd rd. failed to fire (possible follow down) and
 > 4th rd. fired when bolt was being rotated into the closed position (was fully locked
 > when it fired).
 > Note: Safety was off during the 10 rd. test as per my instructions.
 > Measured trigger pull and engagement and then put in my office.

>* Measured trigger pull on guns A-1 to A-20.

>* Measured Indent on guns A-1 to A-20

> 1. During this the bolt stop on gun A-15 (71001464) broke. Broken piece in bag
 > in information pouch. The first indent was taken ok. While closing the bolt to
 > take the second indent the bolt would not close. When the bolt was opened a small metal piece fell out
 > of the gun. At this time it was noticed that the bolt stop was broken. Tagged gun. Out of test for now.

>* Performed Bolt Stop Function Check on guns A-1 to A-20. Did not measure forces yet. Need to

Subject to Protective Order - Williams v. Remington