A ring around a Rem. Mod. 721bolt Discussion Thread Response (Chris) Dear Mr. Thomas, 4/21/2005 10:52:43 AM Thank you for your patience. The ring could be caused by the bolt movement locking into the action and the action touching behind the lugs causing this ring over time. We recommend that you discontinue use and take or ship the Firearm to one of the following Remington Premier Repair Centers for inspection. Send to J & G if you live in the following states: CA, NV, UT, AZ J & G Gunsmithing 625 Vernon St Roseville, CA 95678 916-786-9200 Send to Allison & Carey if you live in the following states: OR, WA, ID, MT, AK Allison & Carey Gun Works, Inc. 17311 SE Stark Portland, OR 97233 Phone: 503-256-5166 Send to Sportsman's Haven if you live in the following states: OH, PA, WV, VA, VT, NH, MD, DE Sportsman's Haven, Inc. 14695 East Pike Rd. Cambridge, OH 43725 Phone: 740-432-7243 Fax: 740-432-3204 Send to Mann & Son if you in the formowing states: IL, IN, MS, AR, WI Mann & Son Sporting Goods 515 W Water St. Pinckneyville, IL Phone: 618-357-2911 Fax: 618-357-3658 62274 Send to Ahlman's if you live in the tollowing states: MN, IA, MO, KS, IN, Send to Allinging SD, ND, WY, NE Ahlman's, Inc. 9525 W. 230th Street Morristown, MN 55052 Phone: 507-685-4244 Fax: 507-685-4280 http://www.ahlmans.com/ Send to Sports World of You live in the following states: OK, TX, NM, CO, Sports World, Inc. 6841East 41st St. Tulsa, OK 74145 Phone: 918-742-4027 Fax: 918-72-3981 Send to Paducah if you live in the following states: KY, TN, NC, SC, GA, Paducah Shooters Supply, Inc. 3919 Cairo St. Paducah, KY 42001

Phone: 270-442-3242 Fax: 270-442-5022

Send to Williams Gun Sight if you live in the following states: MI, NY, CT, RI, NJ, MA, ME
Williams Gun Sight & Outfitters
7389 Lapeer Rd., Route #1
P.O. Box 329
Davidson, MI 48423
Phone: 810-653-2131
Fax: 810-658-2140

You can find additional Remington Warranty Centers for the US and internationally at the following section of our site.

http://www.remington.com/repairsvc/modelselectron.asp

To view the warranty for Remington firearms, go to:

http://www.remington.com/support/warranty.htm

Your rifle was originally installed with a bolt-lock, which means you have to put the safety switch on fire before you can open the bolt. We are offering a conversion at a special price if you would like your firearm converted, so that you can open the bolt at anytime with the safety on safe. To view more details regarding this modification, go to:

http://www.remington.com/Safety\_Red Fication\_Program/remington\_safety.htm

Customer (Floyd Thomas III)

°4/18/2005 9:31:13 PM

Hi, I have a Remington Mod. 721 in .270 win cal. that has a ring/cut all the way around the bolt body 5/16 behind the bolt locking lugs. I am unable to measure the depth but a piece of thread will fit flush into this grove. It would seem to me that this is where the bolt body and locking lugs/bolt head are welded. This cut is even and equal all the way around the bolt so I do not believe this to be any kind of a crack. The fact that the cut is well behind the locking lugs leads me to feel that this is not a safety issue as I do not feel that it could seperate on firing. It seems to me that this bolt was made by Remington this way. What can you folks tell me about this? or what are you folks willing to tell me? Should I be worried about this condition? Please talk to me about this.

Respectfully

Floyd Thomas III 596 Mckinley Ave. Dinuba, CA 93618 559-591-5023 home 559-779-0585 cell 559-227-2540 work bud1\_93618@yahoo.com

PS Any information on this rifle would be appriciated, year and month made and so forth.