M700 MALFUNCTIONS INVOLVING THE TRIGGER CONNECTOR AND SEAR

- 1. INADEQUATE LIFT OF SEAR CAUSES INTERFERENCE AND TRIGGER CONNECTOR TOTALLY FAILS TO SEAT BENEATH SEAR.
- 2. TRIGGER CONNECTOR RIDES UP ON TRIGGER CAUSING INTERFERENCE AND TRIGGER CONNECTOR TOTALLY FAILS TO SEAT BENEATH SEAR.
- 3. TRIGGER CONNECTOR FAILS TO FULLY RETRACT AND THUS PARTIALLY FAILS TO SEAT BENEATH SEAR CAUSING INADEQUATE SUPPORT OF SEAR.