

R 92-1 0008

STANK

FROM: API OUTDOORS INC
C/O GREG PAVIS
602 KIMBROUGH DR
TALLULAH LA 71282

SHIP TO: API OUTDOORS INC
C/O GREG PAVIS
602 KIMBROUGH DR
TALLULAH LA 71282

CUST NO: 060938 C.O.D

ACCOUNT NUMBER		ACCOUNT NUMBER N/C		WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 4/27/82	VIA UPS
GUN CONDITION						REPAIR CHARGE		
☒ NEW	EXCISE							
☐ LIGHTLY WORN	TAX							
☒ WORN	INSURANCE							
☐ VERY WORN	UPS							
☐ UNREPAIRABLE	PARCEL POST							
☐ MARRED					TOTAL			

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	"... sometimes it goes off by itself"					
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

MAIN FAULT Lift cannot be made to malfunction - operates properly in every respect. Assembly of lift (isolated trigger assembly) is overly oily, dirty & rusty. Entire bottom side of receiver and barrel is filthy!! Firearm exhibits no maintenance at all.
Triggers pull 4 3/4 #; over-kill .011"

ARTS	COMMENTS	REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
	Clean entire firearm, if possible! Clean trigger assembly - if just possible, protect flow trigger assembly at + normal cost is a gesture of good-will.	hax					
		GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

FD6925 REV. 1/92

PPS 00200