

All tolerances and dimensions were found to be normal. Trigger pull was measured at 5-1/2 pounds and sear lift with the safety in the on position was well within specifications at .012. Factory seals were intact on the adjustment screws, indicating that no adjustment had been made outside our factory.

Since we found the rifle to be completely correct and function normally in every respect, we are prepared to have the rifle returned in its present condition. However, to restore confidence in the rifle, we will install a new trigger assembly at no charge, as a gesture of customer good-will.

Thank you for allowing us the opportunity to examine the rifle and report our findings, and we trust that our action meets with your approval.

Sincerely,

A handwritten signature in dark ink, appearing to read "D.J. Sanita", written in a cursive style.

D.J. Sanita  
Product Service

DJS:tpp

*Remington Arms Company, Inc.*