


re-set to well below our minimum standard. Overtravel was also set incorrectly outside our factory.

In future use, we strongly recommend that the trigger assembly not be adjusted outside our factory by untrained non-Remington personnel.

As a gesture of customer good-will, we are installing a new, properly adjusted trigger assembly at no-charge. Please allow 2 to 3 weeks for this service to be performed.

Thank you for having afforded us this opportunity to be of service, and we trust that our handling will meet with approval.

Sincerely,

A handwritten signature in cursive script, appearing to read "J.A. Stekl".

J.A. Stekl, Specialist
Product Service

JAS:tpp

Remington Arms Company, Inc.