


lubrication be used sparingly and not let accumulate in or on the trigger assembly.

As a gesture of good-will, we are replacing the trigger assembly and cleaning the action at no-charge. The new trigger assembly will be properly adjusted. Please allow three (3) weeks to have this work completed and return of rifle.

Thank you for allowing us the opportunity to examine this rifle and report our findings, and we trust that our action meets with your approval.

Sincerely,



J.A. Stekl, Specialist
Product Service

JAS: tpp

Remington Arms Company, Inc.