

RECEIVING AND ESTIMATING REPORT

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 11/28/90	DATE OPENED 12/03/90	DATE CODE LQ 2-78	SERIAL NUMBER A6588602	MODEL AND GRADE 700 308 BDL		ORDER R 90-3123	
ACCESSORIES W/STUDS		SCOPE BASE		L/SIGHTS			
FROM: BURNS, J P 2199 S 900 EAST BOUNTIFUL UT 84010				SHIP TO: BURNS, J P 2199 S 900 EAST BOUNTIFUL UT 84010			
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS	

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

SUN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☒ MARRED

CUSTOMER'S REQUEST *"the rifle has discharged on several occasions when the safety has been moved from S to F."*

MAIN FAULT *Trigger assembly is contaminated with gummy residue. Internal parts are not moving freely. As a result, firing pin fall was very slow. The rear-safety cam is sticking to safety trigger housing. Improper maintenance!*

ARTS *Offer to clean present assembly, if possible, or, we can replace the trigger assembly at 1/2 normal cost as a gesture of good-will, if it will better restore confidence in the rifle.*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PPS 00785