

Dec. 760

52. 125-0346

200. 1-6-73

Decided By R. B. Nathan

INDEX

Rt 0526

P. 16

MFD. 7-69

COMMENTS:

7-12-83

- (9) THE CONNECTOR DID NOT APPEAR TO BE TIGHT TO THE TRIGGER.
- (10) THERE APPEARED TO BE A RELATIVELY LARGE AMOUNT OF PLAY BETWEEN TRIGGER AND CONNECTOR.
- (11) THERE WAS FINE SANDY GRIT THROUGHOUT THE HOUSING.
- (12) THERE WERE NO RUFFS AROUND THE TRIGGER HOLE IN THE INSIDE OF THE HOUSING PLATES.
- (13) THE TRIGGER SPRING WAS SHARP AT BOTH ENDS.
- (14) RUS- WAS ON BOTH SIDES OF THE TRIGGER.
- (15) THE SIDE OF THE CONNECTOR WAS SLIGHTLY BULGED ADJACENT TO THE HOLE AND THERE WAS A BRIGHT MARK ON THE BULGE.
- (16) THERE WAS A BUMP ON THE TRIGGER BOTTOM WHERE THE CONNECTOR PIVOTS.
- (17) THE SURFACE ON THE BACK OF THE SEAR WAS NOT AS SMOOTH AS SEARS OBSERVED IN THE PAST.