

# RECEIVING AND ESTIMATING REPORT

COMMENTS  
DELIVERY OF OUR NEW  
L3X40R OPTIC SCREENS

INITIAL	CUSTOMER ORDER NO.				
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER NO.
06/20/91	06/24/91		6234123	700 223 ARMY	R 21-103
ACCESSORIES					
L3 WOOD		SCOPE BASE			

FROM:  <b>CLINTON RIVER GUN SERVICE</b> 30016 S RIVER RD MT. CLEMENS MI 48045	SHIP TO:  <b>CLINTON RIVER GUN SERVICE</b> 30016 S RIVER RD MT. CLEMENS MI 48045
---	--

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED:	VIA
						UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

**GUN CONDITION:**     NEW     SLIGHTLY WORN     VERY WORN     MISUSED     MARRED

CUSTOMER'S REQUEST    *Repair*    *"Firearm does not work when taking safety off"*

**MAIN FAULT**    *Trigger assembly loosened with and improperly adjusted outside factory, as evidenced by foreign yellow sealant - 1) insufficient rear-engagement (as received, firing pin should sometimes not work) 2) trigger pull as received  $\approx$  1 pound - trigger actuation not positive because of excessively light pull weights*

*Offer replacement trigger assembly at no charge, as gesture of good-will.*

REPAIRMAN <i>H/B</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE