

WMM-62


-2-

In summary, it appears that over the years excessive lubrication was allowed to accumulate in the trigger assembly. Under certain circumstances this accumulation could cause the internal parts to hang-up, causing the malfunctions you experienced. In future use, we recommend that oil be used sparingly and not let accumulate in or on the trigger assembly.

We trust that we have clarified the circumstances that may have caused the accidental firings and, to insure that your faith in the rifle is restored, we are replacing the trigger assembly in your rifle at no-charge.

Thank you for having afforded us this opportunity to be of service to you, and we trust that our handling meets with your approval.

Sincerely,

  
J.A. Stekl, Supervisor  
Product Service

JAS:tpg