

make on the trigger outside our company. Trigger pull was within our specifications at 4 pounds. I was seen left with safety in the "on safe" position at 0.512"

The Model 110 test was so designed to have a "dog-leg" configuration on the left handle to position the operators hand forward and away from the trigger when clearing the test. The modification made to the rifle, with the Model 700 left handle, places the hand directly in line with the trigger on hand clearing. We consider this to be an unsafe condition and the probable cause of the incident you described.

Even on our findings, the Remington-Union Arms Company cannot accept any liability or responsibility for the unfortunate incident. We can only assume that accidental contact was made with the trigger in clearing the rifle, as it is common to the rifle design. Therefore, we are returning the rifle to you as we received it.

Thank you for allowing us the opportunity to examine the rifle and report our findings.

Sincerely,

J. J. Miller