


CUSTOMER ORDER NO.		COMMENTS			
RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
22/88	11/30/88	EM 10-65	A6833899	700 30-06 BDL	R 88-31736
SERIES	W/STUDS	W/SWIVELS			

A: **A. DEINTINIS**  
**370 CHAMBERLAIN AVE.**  
**PATERSON, N.J. 07502**

SHIP TO: **A. DEINTINIS**  
**370 CHAMBERLAIN AVE.**  
**PATERSON, N.J. 07502**

INT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED	VIA
				12/5/88	UPS



CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
--------	-----	-----------	-----	-------------	-------

CONDITION:  NEW  SLIGHTLY WORN  VERY WORN  MISUSED  MARRED

MER'S REQUEST

*on several occasions the firing pin did not fall when the trigger was pulled.*

*trigger assembly full of solidified, sticky lubricant - felt this is sticking so is safety cam. Could not duplicate complaint, but entirely possible it happened as stated in cold temperatures*

- 1) Replace trigger assembly with new assembly with bolt lock, at no charge.
  - 2) expedite repair and return of rifle to sender.
- 12/20/88*  
*Jas.*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
JJB					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 6/88