

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-01826

INITIAL **JJM** CUSTOMER ORDER NO.

ATTN DENNIS SANITA CALL TAG
NO CORR

DATE RECEIVED 01/13/94	DATE OPENED 01/14/94	DATE CODE DY 9-74	SERIAL NUMBER 6784235	NEW SERIAL NUMBER	MODEL AND GRADE 700 25-06	EDL
----------------------------------	--------------------------------	-----------------------------	---------------------------------	-------------------	-------------------------------------	------------

ACCESSORIES **W/STUDS SCOPE BASE L/SIGHTS**

FROM: *Handwritten signature*
**DOCKERY, BERTEL
RT 3 BOX 746
GROESBECK**

TX 76642

SHIP TO:
**DOCKERY, BERTEL
RT 3 BOX 746
GROESBECK TX
76642**

JUST NO: 090636 C.O.D.L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	PROM. DATE	ESTIMATED	VIA UPS
UN CONDITION				REPAIR CHARGE 25.00
<input type="checkbox"/> NEW <input type="checkbox"/> LIGHTLY WORN <input type="checkbox"/> WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> UNREPAIRABLE <input type="checkbox"/> MARRED				EXCISE TAX INSURANCE UPS PARCEL POST TOTAL

Handwritten: C.O.D.

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
RIGGER GROUP		B2			E1	F1
OLT ASSY.		B3			E2	F2
ARREL ASSY.		B4			E3	F3
EC. ASSY.		B5		D2	E4	F4
OOD			C1	D3	E5	F5
ETAL			C2			

Handwritten: Found when changing the bolt

IN FAULT: Bolt mfg 1974. Upon receipt, unable to duplicate customer concern. Examination revealed that the action is slipping with a heavy running resistance. Bolt stop release will not retract. Trigger assembly faulty.

COMMENTS

Replace complete trigger assembly and clean action at 1/2 normal replacement cost, superior of good work.

Get ahead - per phone 1/15/94 with Mr. [Signature]

REPAIRMAN	PROOF	CLEAN	TEST	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE

OFFICE COPY

RD6825 REV. 1/92