

R 93-11373

INITIAL J.J.M.	CUSTOMER ORDER NO.				
<i>ATTN J. Kast</i>					
DATE RECEIVED 05/05/93	DATE OPENED 05/06/93	DATE CODE AC 3-82	SERIAL NUMBER B6375990	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06 EDL
ACCESSORIES W/STUDS					
L/REAR SIGHT					
FROM: <i>Stapell</i> DORNS GUN SERVICE 4388 MERCER UNIVERSITY MACON GA 31206			SHIP TO: <i>X.C. F. Supply</i> DORNS GUN SERVICE 4388 MERCER UNIVERSITY MACON GA 31206		

CUST NO: 001078 C.O.D.L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------	------------

GUN CONDITION	REPAIR CHARGE
<input checked="" type="checkbox"/> NEW <i>Macomber</i>	EXCISE
<input type="checkbox"/> LIGHTLY WORN	TAX
<input type="checkbox"/> WORN	INSURANCE
<input type="checkbox"/> VERY WORN	UPS
<input type="checkbox"/> UNREPAIRABLE	PARCEL POST
<input type="checkbox"/> MARRED	TOTAL <i>2</i>

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3		D1	E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *Self inf 1982 - Unable to duplicate Customer concern. Examination revealed safety mechanism in action, and trigger adjustment on trigger assembly had full stop return. This substituted assembly to be supplied. The trigger adjustment now has been temporary with replace safety.*

COMMENTS *Send to product source for evaluation. R. Smith*

*Repair complete trigger assembly at 1/2 normal replacement cost & clear action as given & good will*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD5925 REV. 1/91