

-2-

Trigger pull was measured to be 4 3/4", and sear lift with the safety in the "on-safe" position was well within specifications at .011". The only manner in which the rifle could be made to fire was with the safety off and the trigger, pulled, as designed. Inadvertent contact with the trigger while releasing the safety could cause a rifle to fire, which will occur with all popular bolt action rifles.

Since we found your firearm to be completely correct and to function normally in every respect, the Remington Arms Company, Inc. cannot assume any responsibility or liability for the alleged accidental firings, and are returning the rifle to you as received.

Thank you for affording us the opportunity to examine your rifle and report our findings.

Sincerely,



J.A. Stekl  
Supervisor

JAS:nb