

INITIAL	CUSTOMER ORDER NO.		DATE RECEIVED		DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE		ORDER
LCS	3818		10/02/90	10/10/90	KH 5-87	B6862048	700	270	BDL	R 90-2
ACCESSORIES		W/STUDS		L/SIGHTS						

FROM:	SHIP TO:
EWELL CROSS GUN SHOP P.O. BOX 3025 8240 I-30 WEST FT WORTH TX 76108	EWELL CROSS GUN SHOP P.O. BOX 3025 8240 I-30 WEST FT WORTH TX 76108

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
						UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION: NEW SLIGHTLY WORN VERY WORN MISUSED MARRED

CUSTOMER'S REQUEST
"This gun fired when the safety was pushed off"

MAIN FAULT
Entire trigger assembly is contaminated with a sticky residue (WD-40). The rear-safety cam is stuck solidly to the side plate of the trigger assembly and is inoperative. Rifle has not been properly maintained.

PARTS
Send quotation to replace trigger assembly at normal price, as system of gun will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
<i>BA</i>					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE