

RECEIVING AND ESTIMATING REPORT

#30

| | | | | | |
|---------------|-------------|--------------------|---------------|-----------------|-------|
| INITIAL | | CUSTOMER ORDER NO. | | COMMENTS | |
| RLP | | 722-3741 | | | |
| DATE RECEIVED | DATE OPENED | DATE CODE | SERIAL NUMBER | MODEL AND GRADE | ORDER |
| 09/14/90 | 09/26/90 | RI 11-88 | 08323698 | 78 39-06 SPT. | R |

| | | |
|---|---|--|
| ACCESSORIES | | |
| FROM: | SHIP TO: | |
| GASSER TRUE VALUE HDWE HWY 61 N P O BOX 424 LANCASTER WI 53813 | GASSER TRUE VALUE HDWE HWY 61 N P O BOX 424 LANCASTER WI 53813 | |

| | | | | | |
|----------------|--------------------|--------------------------------|------------|-----------|---------|
| ACCOUNT NUMBER | ACCOUNT NUMBER N/C | WRITE <input type="checkbox"/> | PROM. DATE | ESTIMATED | VIA UPS |
|----------------|--------------------|--------------------------------|------------|-----------|---------|

| | | | | | |
|---------------|-----|-----------|-----|-------------|-------|
| REPAIR CHARGE | TAX | INSURANCE | UPS | PARCEL POST | TOTAL |
|---------------|-----|-----------|-----|-------------|-------|

GUN CONDITION:

NEW
 SLIGHTLY WORN
 VERY WORN
 MISUSED
 MARRED

CUSTOMER'S REQUEST: *"... firing at will"*

MAIN FAULT: *Tugger assembly rusted from unknown cause. Internal tugger parts not moving freely assembly not operating properly.*

PARTS: *Replace tugger assembly at no-charge.*

| | | | | | |
|----------------|-------|-------|------|--------|---------|
| REPAIRMAN | PROOF | CLEAN | TEST | TARGET | PATTERN |
| GALLERY TESTER | DATE | DATE | DATE | DATE | DATE |

RD6925 REV. 6-88