

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-04079

INITIAL P.S.	CUSTOMER ORDER NO.					
DATE RECEIVED 02/01/94	DATE OPENED 02/02/94	DATE CODE BX 1-73	SERIAL NUMBER 6605591	NEW SERIAL NUMBER	MODEL AND GRADE 700 22-250	BDL.
ACCESSORIES W/STUDS		SCOPE BASE		L/SIGHTS		

FROM: <i>[Signature]</i> GEISERS GUNS 170 LENKER ST SUNBURY PA 17801	SHIP TO: GEISERS GUNS 170 LENKER ST SUNBURY PA 17801
--	---

CUST NO: 005387 WILM

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------	------------

GUN CONDITION <input type="checkbox"/> NEW <input type="checkbox"/> LIGHTLY WORN <input checked="" type="checkbox"/> WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> UNREPAIRABLE <input type="checkbox"/> MARRED	REPAIR CHARGE <i>RE</i>
	EXCISE
	TAX
	INSURANCE
	UPS
	PARCEL POST
	TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	<i>lined when safety was moved</i>				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *Upon receipt, unable to duplicate customer concern. However, examination of trigger assembly revealed that adjustment had been applied to the 3 adjustment screws. Trigger pull was measured at over min spec. After much good cleaning, with Feb 1993. Adjustment appears to have been changed with out the policy.*

COMMENTS *Customer complaint trigger issue. I clean entire set for second cost, as per our good will. Go ahead*

REPAIRMAN <i>[Signature]</i>	PROOF	CLEAN	TEST	TARGET	PAT
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6325 RE